



Kelly Miller Middle School Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009702	2/21/2023	2/21/2024	1	Cooler	In cafeteria	WF-02212023-009702	1/21/2024	FT-FY24-11272023-009702-A	<1	FT-FY24-11272023-009702-B	<1
WS- 009708	2/21/2023	2/21/2024	1	Bottle Filler	In cafeteria	WF-02212023-009708	1/21/2024	FT-FY24-11272023-009708-A	<1	FT-FY24-11272023-009708-B	<1
WS- 009711	2/21/2023	2/21/2024	1	Cooler	In hallway adjacent to room A118 High Left	WF-02212023-009711	1/21/2024	FT-FY24-11272023-009711-A	<1	FT-FY24-11272023-009711-B	<1
WS- 009712	2/21/2023	2/21/2024	1	Cooler	In hallway adjacent to room A118 Low Right	WF-02212023-009712	1/21/2024	FT-FY24-11272023-009712-A	<1	FT-FY24-11272023-009712-B	1.3
WS- 009733	2/21/2023	2/21/2024	1	Cooler	In hallway across from room C123 Low Left	WF-02212023-009733	1/21/2024	FT-FY24-11272023-009733-A	<1	FT-FY24-11272023-009733-B	<1
WS- 009734	2/21/2023	2/21/2024	1	Cooler	In hallway across from room C123 High Right	WF-02212023-009734	1/21/2024	FT-FY24-11272023-009734-A	<1	FT-FY24-11272023-009734-B	<1
WS- 009735	2/21/2023	2/21/2024	2	Cooler	In hallway adjacent to room A218 High Left	WF-02212023-009735	1/21/2024	FT-FY24-11272023-009735-A	<1	FT-FY24-11272023-009735-B	<1
WS- 009736	2/21/2023	2/21/2024	2	Cooler	In hallway adjacent to room A218 Low Right	WF-02212023-009736	1/21/2024	FT-FY24-11272023-009736-A	<1	FT-FY24-11272023-009736-B	<1
WS- 009737	2/21/2023	2/21/2024	2	Cooler	In hallway adjacent to elevator High Left	WF-02212023-009737	1/21/2024	FT-FY24-11272023-009737-A	<1	FT-FY24-11272023-009737-B	<1
WS- 009738	2/21/2023	2/21/2024	2	Cooler	In hallway adjacent to elevator Low Right	WF-02212023-009738	1/21/2024	FT-FY24-11272023-009738-A	<1	FT-FY24-11272023-009738-B	<1
WS- 009739	2/21/2023	2/21/2024	2	Break Room	In staff lounge kitchen	WF-02212023-009739	1/21/2024	FT-FY24-11272023-009739-A	<1	FT-FY24-11272023-009739-B	<1
WS- 009758	2/21/2023	2/21/2024	3	Cooler	In hallway adjacent to boys' restroom High Right	WF-02212023-009758	1/21/2024	FT-FY24-11272023-009758-A	<1	FT-FY24-11272023-009758-B	<1
WS- 009759	2/21/2023	2/21/2024	3	Cooler	In hallway adjacent to boys' restroom Low Left	WF-02212023-009759	1/21/2024	FT-FY24-11272023-009759-A	<1	FT-FY24-11272023-009759-B	<1
WS- 009779	2/21/2023	2/21/2024	3	Break Room	In workroom A325	WF-02212023-009779	1/21/2024	FT-FY24-11272023-009779-A	<1	FT-FY24-11272023-009779-B	<1
WS- 009780	2/21/2023	2/21/2024	2	Break Room	In workroom A227	WF-02212023-009780	1/21/2024	FT-FY24-11272023-009780-A	<1	FT-FY24-11272023-009780-B	<1
WS- 009781	2/21/2023	2/21/2024	3	Break Room	In workroom A327	WF-02212023-009781	1/21/2024	FT-FY24-11272023-009781-A	<1	FT-FY24-11272023-009781-B	<1
WS- 009782	2/21/2023	2/21/2024	2	Break Room	In workroom A226	WF-02212023-009782	1/21/2024	FT-FY24-11272023-009782-A	<1	FT-FY24-11272023-009782-B	<1
WS- 009786	2/21/2023	2/21/2024	1	Health Suite	In health suite B112	WF-02212023-009786	1/21/2024	FT-FY24-11272023-009786-A	<1	FT-FY24-11272023-009786-B	<1
WS- 009787	2/21/2023	2/21/2024	1	Break Room	In workroom B116	WF-02212023-009787	1/21/2024	FT-FY24-11272023-009787-A	<1	FT-FY24-11272023-009787-B	<1
WS- 009807	2/27/2023	2/27/2024	1	Combo Fountain	In Room 135	WF-02272023-009807	1/21/2024	FT-FY24-11272023-009807-A	<1	FT-FY24-11272023-009807-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009706	1/13/2023	1/13/2024	1	Food Prep Sink	In kitchen across from room D114	WF-01132023-009706	1/21/2024	FT-FY24-11272023-009706-A	<1	FT-FY24-11272023-009706-B	<1