



# KELLY MILLER MS LEAD WATER TEST



## Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	KELLY MILLER MS	WS- 009779	2/8/2017	3	Break Room	In workroom A325	FT-102016-009779-A	< 1	FT-102016-009779-B	< 1
2	KELLY MILLER MS	WS- 009780	2/8/2017	2	Break Room	In workroom A227	FT-102016-009780-A	< 1	FT-102016-009780-B	< 1

Note :  
Filter re-tests are only performed to devices that have sampling results greater than 1 ppb