



KELLY MILLER POOL LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 KELLY MILLER POOL	5/26/2016	WS- 012020	Cooler	Ground Floor	Adjacent to pool house Right High	WT-042916-12037- A	< 1	WT-042916-12037- B	< 1				
2 KELLY MILLER POOL	5/26/2016	WS- 012021	Cooler	Ground Floor	Adjacent to pool house Left Low	WT-042916-12038- A	< 1	WT-042916-12038- B	< 1				
3 KELLY MILLER POOL	5/26/2016	WS- 012022	Health Suite	Ground Floor	In first aid office	WT-042916-12039- A	< 1	WT-042916-12039- B	< 1				
4 KELLY MILLER POOL	5/26/2016	WS- 012023	Bathroom	Ground Floor	In office restroom (closest tap to main source)	WT-042916-12040- A	9.8	WT-042916-12040- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.