



Kelly Miller MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009702	10/15/2018	10/15/2019	1	Cooler	In cafeteria	WF-10152018-009702	12/18/2018	FT-FY19-122018-009702-A	<1	FT-FY19-122018-009702-B	<1
WS-009710	4/2/2018	4/2/2019	1	Cooler	In hallway adjacent to elevator Low Right	WF-04022018-009710	12/18/2018	FT-FY19-122018-009710-A	<1	FT-FY19-122018-009710-B	<1
WS-009711	4/2/2018	4/2/2019	1	Cooler	In hallway adjacent to room A118 High Left	WF-04022018-009711	12/18/2018	FT-FY19-122018-009711-A	<1	FT-FY19-122018-009711-B	<1
WS-009712	4/2/2018	4/2/2019	1	Cooler	In hallway adjacent to room A118 Low Right	WF-04022018-009712	12/18/2018	FT-FY19-122018-009712-A	<1	FT-FY19-122018-009712-B	<1
WS-009716	4/2/2018	4/2/2019	1	Cooler	In gym adjacent to D122	WF-04022018-009716	12/18/2018	FT-FY19-122018-009716-A	<1	FT-FY19-122018-009716-B	<1
WS-009717	10/15/2018	10/15/2019	1	Cooler	In gym adjacent to girls' locker room	WF-10152018-009717	12/18/2018	FT-FY19-122018-009717-A	<1	FT-FY19-122018-009717-B	<1
WS-009733	10/15/2018	10/15/2019	1	Cooler	In hallway across from room C123 Low Left	WF-10152018-009733	12/18/2018	FT-FY19-122018-009733-A	<1	FT-FY19-122018-009733-B	<1
WS-009734	10/15/2018	10/15/2019	1	Cooler	In hallway across from room C123 High Right	WF-10152018-009734	12/18/2018	FT-FY19-122018-009734-A	<1	FT-FY19-122018-009734-B	<1
WS-009735	10/16/2018	10/16/2019	2	Cooler	In hallway adjacent to room A218 High Left	WF-10162018-009735	12/18/2018	FT-FY19-122018-009735-A	<1	FT-FY19-122018-009735-B	<1
WS-009736	10/16/2018	10/16/2019	2	Cooler	In hallway adjacent to room A218 Low Right	WF-10162018-009736	12/18/2018	FT-FY19-122018-009736-A	<1	FT-FY19-122018-009736-B	<1
WS-009737	4/2/2018	4/2/2019	2	Cooler	In hallway adjacent to elevator High Left	WF-04022018-009737	12/18/2018	FT-FY19-122018-009737-A	<1	FT-FY19-122018-009737-B	<1
WS-009738	4/2/2018	4/2/2019	2	Cooler	In hallway adjacent to elevator Low Right	WF-04022018-009738	12/18/2018	FT-FY19-122018-009738-A	<1	FT-FY19-122018-009738-B	<1
WS-009739	4/2/2018	4/2/2019	2	Break Room	In staff lounge kitchen	WF-04022018-009739	12/18/2018	FT-FY19-122018-009739-A	<1	FT-FY19-122018-009739-B	<1
WS-009758	4/2/2018	4/2/2019	3	Cooler	In hallway adjacent to boys' restroom High Right	WF-04022018-009758	12/18/2018	FT-FY19-122018-009758-A	<1	FT-FY19-122018-009758-B	<1
WS-009759	4/2/2018	4/2/2019	3	Cooler	In hallway adjacent to boys' restroom Low Left	WF-04022018-009759	12/18/2018	FT-FY19-122018-009759-A	<1	FT-FY19-122018-009759-B	<1
WS-009760	4/2/2018	4/2/2019	3	Cooler	In hallway adjacent to elevator High Right	WF-04022018-009760	12/18/2018	FT-FY19-122018-009760-A	<1	FT-FY19-122018-009760-B	<1
WS-009761	4/2/2018	4/2/2019	3	Cooler	In hallway adjacent to elevator Low Left	WF-04022018-009761	12/18/2018	FT-FY19-122018-009761-A	<1	FT-FY19-122018-009761-B	<1
WS-009779	4/2/2018	4/2/2019	3	Break Room	In workroom A325	WF-04022018-009779	12/18/2018	FT-FY19-122018-009779-A	<1	FT-FY19-122018-009779-B	<1
WS-009780	4/2/2018	4/2/2019	2	Break Room	In workroom A227	WF-04022018-009780	12/18/2018	FT-FY19-122018-009780-A	<1	FT-FY19-122018-009780-B	<1
WS-009781	4/2/2018	4/2/2019	3	Break Room	In workroom A327	WF-04022018-009781	12/18/2018	FT-FY19-122018-009781-A	<1	FT-FY19-122018-009781-B	<1
WS-009782	4/2/2018	4/2/2019	2	Break Room	In workroom A226	WF-04022018-009782	12/18/2018	FT-FY19-122018-009782-A	<1	FT-FY19-122018-009782-B	<1
WS-009786	4/2/2018	4/2/2019	1	Health Suite	In health suite B112	WF-04022018-009786	12/18/2018	FT-FY19-122018-009786-A	<1	FT-FY19-122018-009786-B	<1
WS-009787	4/2/2018	4/2/2019	1	Break Room	In workroom B116	WF-04022018-009787	12/18/2018	FT-FY19-122018-009787-A	<1	FT-FY19-122018-009787-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation									
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-009706	1	Food Prep Sink	In kitchen across from room D114	12/18/2018	FT-FY19-122018-009706-A	<1	FT-FY19-122018-009706-B	<1	
WS-009785	1	Food Prep Sink	In kitchen across from room D106	12/18/2018	FT-FY19-122018-009785-A	<1	FT-FY19-122018-009785-B	<1	