



Kenilworth Parkside RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007000	11/5/2018	11/5/2019	1	Bottle Filler	In hallway adjacent to fitness room 106	WF-11052018-007000	3/13/2019	FT-FY19-032019-007000-A	<1	FT-FY19-032019-007000-B	<1
WS- 007001	11/5/2018	11/5/2019	1	Cooler	In hallway adjacent to fitness room 106	WF-11052018-007001	3/13/2019	FT-FY19-032019-007001-A	<1	FT-FY19-032019-007001-B	<1
WS- 007002	11/5/2018	11/5/2019	1	Bottle Filler	In hallway adjacent to multipurpose room 108A	WF-11052018-007002	3/13/2019	FT-FY19-032019-007002-A	<1	FT-FY19-032019-007002-B	<1
WS- 007003	11/5/2018	11/5/2019	1	Cooler	In hallway adjacent to multipurpose room 108A Low Left	WF-11052018-007003	3/13/2019	FT-FY19-032019-007003-A	<1	FT-FY19-032019-007003-B	<1
WS- 007004	11/5/2018	11/5/2019	1	Cooler	In hallway adjacent to multipurpose room 108A High Right	WF-11052018-007004	3/13/2019	FT-FY19-032019-007004-A	<1	FT-FY19-032019-007004-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007005	2/21/2019	2/21/2020	1	Food Prep Sink	In 114 kitchen second clockwise from entrance	WF-02212019-007005	3/13/2019	FT-FY19-032019-007005-A	<1	FT-FY19-032019-007005-B	<1