



# Kenilworth Parkside RC Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007000	5/8/2019	5/8/2020	1	Bottle Filler	In hallway adjacent to fitness room 106	WF-05082019-007000	3/11/2020	FT-FY20-012020-007000-A	<1	FT-FY20-012020-007000-B	<1
WS- 007001	5/8/2019	5/8/2020	1	Cooler	In hallway adjacent to fitness room 106	WF-05082019-007001	3/11/2020	FT-FY20-012020-007001-A	<1	FT-FY20-012020-007001-B	<1
WS- 007002	5/8/2019	5/8/2020	1	Bottle Filler	In hallway adjacent to multipurpose room 108A	WF-05082019-007002	3/11/2020	FT-FY20-012020-007002-A	<1	FT-FY20-012020-007002-B	<1
WS- 007003	5/8/2019	5/8/2020	1	Cooler	In hallway adjacent to multipurpose room 108A	WF-05082019-007003	3/11/2020	FT-FY20-012020-007003-A	<1	FT-FY20-012020-007003-B	<1
WS- 007004	5/8/2019	5/8/2020	1	Cooler	In hallway adjacent to multipurpose room 108A	WF-05082019-007004	3/11/2020	FT-FY20-012020-007004-A	<1	FT-FY20-012020-007004-B	<1
WS- 007005	5/8/2019	5/8/2020	1	Food Prep Sink	In 114 kitchen second clockwise from entrance	WF-05082019-007005	3/11/2020	FT-FY20-012020-007005-A	1.3	FT-FY20-012020-007005-B	<1