



# Kenilworth Parkside Recreation Center Lead in Water Test Results

## FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007000	5/4/2022	5/4/2023	1	Bottle Filler	In hallway adjacent to fitness room 106	WF-05042022-007000	2/21/2023	FT-FY23-02022023-007000-A	<1	FT-FY23-02022023-007000-B	<1
WS- 007001	5/4/2022	5/4/2023	1	Cooler	In hallway adjacent to fitness room 106	WF-05042022-007001	2/21/2023	FT-FY23-02022023-007001-A	<1	FT-FY23-02022023-007001-B	<1
WS- 007005	1/18/2023	1/18/2024	1	Food Prep Sink	In 114 kitchen second clockwise from entrance	WF-01182023-007005	2/21/2023	FT-FY23-02022023-007005-A	<1	FT-FY23-02022023-007005-B	<1