



Kenilworth-Parkside Recreation Center Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 007000	4/9/2024	4/9/2025	1	Bottle Filler	In hallway adjacent to fitness room 106	WF-04092024-007000	5/3/2024	FT-FY24-04172024-007000-A	<1	FT-FY24-04172024-007000-B	<1
WS- 007001	4/9/2024	4/9/2025	1	Cooler	In hallway adjacent to fitness room 106	WF-04092024-007001	5/3/2024	FT-FY24-04172024-007001-A	<1	FT-FY24-04172024-007001-B	<1
WS- 007005	12/6/2023	12/6/2024	1	Food Prep Sink	In 114 kitchen second clockwise from entrance	WF-12062023-007005	5/3/2024	FT-FY24-04172024-007005-A	<1	FT-FY24-04172024-007005-B	<1