



Kenilworth Swing Space Lead in Water Test Results

FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 000417	5/15/2023	5/15/2024	1	Cooler	In 119 health suite	WF-05152023-000417	10/16/2023	FT-FY24-09282023-000417-A	<1	FT-FY24-09282023-000417-B	<1	
WS- 000418	5/15/2023	5/15/2024	1	Cooler	In 102 library	WF-05152023-000418	10/16/2023	FT-FY24-09282023-000418-A	<1	FT-FY24-09282023-000418-B	<1	
WS- 000419	5/15/2023	5/15/2024	1	Cooler	In hallway adjacent to 101	WF-05152023-000419	10/16/2023	FT-FY24-09282023-000419-A	<1	FT-FY24-09282023-000419-B	<1	
WS- 000421	5/15/2023	5/15/2024	2	Cooler	In hallway adjacent to 213	WF-05152023-000421	10/16/2023	FT-FY24-09282023-000421-A	<1	FT-FY24-09282023-000421-B	<1	
WS- 000422	5/15/2023	5/15/2024	2	Cooler	In hallway adjacent to 201	WF-05152023-000422	10/16/2023	FT-FY24-09282023-000422-A	<1	FT-FY24-09282023-000422-B	<1	
WS- 000423	5/15/2023	5/15/2024	2	Cooler	In hallway adjacent to girls' restroom	WF-05152023-000423	10/16/2023	FT-FY24-09282023-000423-A	<1	FT-FY24-09282023-000423-B	<1	
WS- 000424	5/15/2023	5/15/2024	2	Cooler	In hallway adjacent to 231	Low Right	WF-05152023-000424	10/16/2023	FT-FY24-09282023-000424-A	<1	FT-FY24-09282023-000424-B	<1
WS- 000425	5/15/2023	5/15/2024	3	Break Room	In 304 staff lounge	WF-05152023-000425	10/16/2023	FT-FY24-09282023-000425-A	<1	FT-FY24-09282023-000425-B	<1	
WS- 000426	5/15/2023	5/15/2024	3	Cooler	In hallway adjacent to 313	WF-05152023-000426	10/16/2023	FT-FY24-09282023-000426-A	<1	FT-FY24-09282023-000426-B	<1	
WS- 000427	5/15/2023	5/15/2024	Ground Floor	Bottle Filler	In cafeteria bubble	WF-05152023-000427	10/16/2023	FT-FY24-09282023-000427-A	<1	FT-FY24-09282023-000427-B	<1	
WS- 000428	5/15/2023	5/15/2024	Ground Floor	Cooler	In cafeteria bubble	High Left	WF-05152023-000428	10/16/2023	FT-FY24-09282023-000428-A	<1	FT-FY24-09282023-000428-B	<1
WS- 000429	5/15/2023	5/15/2024	Ground Floor	Cooler	In cafeteria bubble	Low Right	WF-05152023-000429	10/16/2023	FT-FY24-09282023-000429-A	<1	FT-FY24-09282023-000429-B	<1
WS- 000717	5/15/2023	5/15/2024	1	Bottle Filler	In 119 health suite	WF-05152023-000717	10/16/2023	FT-FY24-09282023-000717-A	<1	FT-FY24-09282023-000717-B	<1	
WS- 000719	5/15/2023	5/15/2024	1	Bottle Filler	In hallway adjacent to 101	WF-05152023-000719	10/16/2023	FT-FY24-09282023-000719-A	<1	FT-FY24-09282023-000719-B	<1	
WS- 000779	5/15/2023	5/15/2024	2	Bottle Filler	In hallway adjacent to 201	WF-05152023-000779	10/16/2023	FT-FY24-09282023-000779-A	<1	FT-FY24-09282023-000779-B	<1	
WS- 000781	5/15/2023	5/15/2024	2	Bottle Filler	In hallway adjacent to 213	WF-05152023-000781	10/16/2023	FT-FY24-09282023-000781-A	<1	FT-FY24-09282023-000781-B	<1	
WS- 000782	5/15/2023	5/15/2024	2	Bottle Filler	In hallway adjacent to 231	WF-05152023-000782	10/16/2023	FT-FY24-09282023-000782-A	<1	FT-FY24-09282023-000782-B	<1	
WS- 000790	5/15/2023	5/15/2024	2	Cooler	In hallway adjacent to 231	High Left	WF-05152023-000790	10/16/2023	FT-FY24-09282023-000790-A	<1	FT-FY24-09282023-000790-B	<1
WS- 000791	5/15/2023	5/15/2024	2	Bottle Filler	In hallway adjacent to girls' restroom	WF-05152023-000791	10/16/2023	FT-FY24-09282023-000791-A	<1	FT-FY24-09282023-000791-B	<1	
WS- 000803	5/15/2023	5/15/2024	3	Bottle Filler	In hallway adjacent to 313	WF-05152023-000803	10/16/2023	FT-FY24-09282023-000803-A	<1	FT-FY24-09282023-000803-B	<1	

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000432	1/24/2023	1/24/2024	Ground Floor	Food Prep Sink	In kitchen trailer 1st clockwise from outdoor entry	WF-01242023-000432	10/16/2023	FT-FY24-09282023-000432-A	<1	FT-FY24-09282023-000432-B	<1