



# Ketcham ES Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009605	5/24/2017	5/24/2018	Ground Floor	Cooler	In hallway adjacent to girls' restroom	WF-52017-009605	11/21/2017	FT-FY18--52017-009605-A	<1	FT-FY18--52017-009605-B	<1
WS- 009606	5/24/2017	5/24/2018	1	Cooler	In hallway adjacent to room A-102	WF-52017-009606	11/21/2017	FT-FY18--52017-009606-A	<1	FT-FY18--52017-009606-B	<1
WS- 009608	5/24/2017	5/24/2018	1	Combo Fountain	In classroom A-101	WF-52017-009608	11/21/2017	FT-FY18--52017-009608-A	<1	FT-FY18--52017-009608-B	<1
WS- 009611	5/24/2017	5/24/2018	1	Cooler	In hallway across from room B-109	WF-52017-009611	11/21/2017	FT-FY18--52017-009611-A	<1	FT-FY18--52017-009611-B	<1
WS- 009614	5/24/2017	5/24/2018	1	Combo Fountain	In classroom B-113	WF-52017-009614	11/21/2017	FT-FY18--52017-009614-A	<1	FT-FY18--52017-009614-B	<1
WS- 009617	11/7/2017	11/7/2018	1	Combo Faucet	In classroom B-114	WF-112017-009617	11/21/2017	FT-FY18-112017-009617-A	<1	FT-FY18-112017-009617-B	<1
WS- 009618	5/24/2017	5/24/2018	1	Combo Fountain	In classroom B-116	WF-52017-009618	11/21/2017	FT-FY18--52017-009618-A	<1	FT-FY18--52017-009618-B	<1
WS- 009622	5/24/2017	5/24/2018	2	Break Room	In staff lounge B-202	WF-52017-009622	11/21/2017	FT-FY18--52017-009622-A	<1	FT-FY18--52017-009622-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009602	Ground Floor	Food Prep Sink	In kitchen on north wall Left	11/21/2017	FT-FY18-102017-009602-A	1.5	FT-FY18-102017-009602-B	<1