



# Ketcham ES Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009604	7/26/2018	7/26/2019	Ground Floor	Cooler	In cafeteria	WF-07262018-009604	11/2/2018	FT-FY19-102018-009604-A	< 1	FT-FY19-102018-009604-B	< 1
WS-009606	10/4/2018	10/4/2019	1	Cooler	In hallway adjacent to room A-102	WF-10042018-009606	11/2/2018	FT-FY19-102018-009606-A	< 1	FT-FY19-102018-009606-B	< 1
WS-009607	10/16/2018	10/16/2019	1	Combo Faucet	In classroom A-101	WF-10162018-009607	11/2/2018	FT-FY19-102018-009607-A	< 1	FT-FY19-102018-009607-B	< 1
WS-009608	4/10/2018	4/10/2019	1	Combo Fountain	In classroom A-101	WF-04102018-009608	11/2/2018	FT-FY19-102018-009608-A	< 1	FT-FY19-102018-009608-B	< 1
WS-009610	4/10/2018	4/10/2019	1	Health Suite	In health suite 105	WF-04102018-009610	11/2/2018	FT-FY19-102018-009610-A	< 1	FT-FY19-102018-009610-B	< 1
WS-009611	10/4/2018	10/4/2019	1	Cooler	In hallway across from room B-109	WF-10042018-009611	11/2/2018	FT-FY19-102018-009611-A	< 1	FT-FY19-102018-009611-B	< 1
WS-009612	4/10/2018	4/10/2019	1	Combo Fountain	In classroom B-109	WF-04102018-009612	11/2/2018	FT-FY19-102018-009612-A	< 1	FT-FY19-102018-009612-B	< 1
WS-009613	10/16/2018	10/16/2019	1	Combo Faucet	In classroom B-109	WF-10162018-009613	11/2/2018	FT-FY19-102018-009613-A	< 1	FT-FY19-102018-009613-B	< 1
WS-009614	4/10/2018	4/10/2019	1	Combo Fountain	In classroom B-113	WF-04102018-009614	11/2/2018	FT-FY19-102018-009614-A	1.3	FT-FY19-102018-009614-B	1
WS-009615	10/16/2018	10/16/2019	1	Combo Faucet	In classroom B-113	WF-10162018-009615	11/2/2018	FT-FY19-102018-009615-A	< 1	FT-FY19-102018-009615-B	< 1
WS-009616	9/7/2018	9/7/2019	1	Combo Fountain	In classroom B-114	WF-09072018-009616	11/2/2018	FT-FY19-102018-009616-A	< 1	FT-FY19-102018-009616-B	< 1
WS-009617	10/16/2018	10/16/2019	1	Combo Faucet	In classroom B-114	WF-10162018-009617	11/2/2018	FT-FY19-102018-009617-A	< 1	FT-FY19-102018-009617-B	< 1
WS-009618	4/10/2018	4/10/2019	1	Combo Fountain	In classroom B-116	WF-04102018-009618	11/2/2018	FT-FY19-102018-009618-A	< 1	FT-FY19-102018-009618-B	< 1
WS-009619	10/16/2018	10/16/2019	1	Combo Faucet	In classroom B-116	WF-10162018-009619	11/2/2018	FT-FY19-102018-009619-A	< 1	FT-FY19-102018-009619-B	< 1
WS-009622	4/10/2018	4/10/2019	2	Break Room	In staff lounge B-202	WF-04102018-009622	11/2/2018	FT-FY19-102018-009622-A	< 1	FT-FY19-102018-009622-B	< 1
WS-009624	9/7/2018	9/7/2019	2	Cooler	In hallway adjacent restroom	WF-09072018-009624	11/2/2018	FT-FY19-102018-009624-A	< 1	FT-FY19-102018-009624-B	< 1
WS-009631	7/26/2018	7/26/2019	2	Cooler	In hallway adjacent to room 205	WF-07262018-009631	11/2/2018	FT-FY19-102018-009631-A	< 1	FT-FY19-102018-009631-B	< 1
WS-009634	4/10/2018	4/10/2019	3	Break Room	In staff lounge B-302	WF-04102018-009634	11/2/2018	FT-FY19-102018-009634-A	< 1	FT-FY19-102018-009634-B	1
WS-009636	10/4/2018	10/4/2019	3	Cooler	In hallway adjacent to stairwell 2	WF-10042018-009636	11/2/2018	FT-FY19-102018-009636-A	< 1	FT-FY19-102018-009636-B	< 1
WS-009792	10/23/2018	10/23/2019	Ground Floor	Combo Fountain	In classroom B101	WF-10232018-009792	11/2/2018	FT-FY19-102018-009792-A	< 1	FT-FY19-102018-009792-B	< 1
WS-009793	10/23/2018	10/23/2019	Ground Floor	Break Room	In break room B109	WF-10232018-009793	11/2/2018	FT-FY19-102018-009793-A	< 1	FT-FY19-102018-009793-B	< 1
WS-009794	10/23/2018	10/23/2019	Ground Floor	Combo Faucet	In classroom B104	WF-10232018-009794	11/2/2018	FT-FY19-102018-009794-A	< 1	FT-FY19-102018-009794-B	< 1
WS-009795	10/23/2018	10/23/2019	Ground Floor	Combo Fountain	In classroom B104	WF-10232018-009795	11/2/2018	FT-FY19-102018-009795-A	< 1	FT-FY19-102018-009795-B	< 1
WS-009796	10/23/2018	10/23/2019	Ground Floor	Combo Faucet	In classroom B103	WF-10232018-009796	11/2/2018	FT-FY19-102018-009796-A	< 1	FT-FY19-102018-009796-B	1.4
WS-009797	10/23/2018	10/23/2019	Ground Floor	Combo Fountain	In classroom B103	WF-10232018-009797	11/2/2018	FT-FY19-102018-009797-A	< 1	FT-FY19-102018-009797-B	< 1
WS-009798	10/23/2018	10/23/2019	Ground Floor	Combo Faucet	In classroom B101	WF-10232018-009798	11/2/2018	FT-FY19-102018-009798-A	< 1	FT-FY19-102018-009798-B	< 1
WS-009799	5/3/2018	5/3/2019	1	Break Room	In staff office room B-117	WF-05032018-009799	11/2/2018	FT-FY19-102018-009799-A	< 1	FT-FY19-102018-009799-B	< 1
WS-009800	10/23/2018	10/23/2019	Ground Floor	Bottle Filler	In hallway adjacent to classroom B104	WF-10232018-009800	11/2/2018	FT-FY19-102018-009800-A	< 1	FT-FY19-102018-009800-B	< 1
WS-009801	10/23/2018	10/23/2019	Ground Floor	Cooler	In hallway adjacent to classroom B104 High Right	WF-10232018-009801	11/2/2018	FT-FY19-102018-009801-A	< 1	FT-FY19-102018-009801-B	< 1
WS-009802	10/23/2018	10/23/2019	Ground Floor	Cooler	In hallway adjacent to classroom B104 Low Left	WF-10232018-009802	11/2/2018	FT-FY19-102018-009802-A	< 1	FT-FY19-102018-009802-B	< 1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
-----------	-----------------------	------------------------	-------	-------------	-----------------	---------------------	---------------	----------------------	----------------------------------	----------------------	----------------------------------

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009602	Ground Floor	Food Prep Sink	In kitchen on north wall Left	11/2/2018	FT-FY19-102018-009602-A	< 1	FT-FY19-102018-009602-B	< 1