



KIMBALL ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	KIMBALL ELEMENTARY SCHOOL	WS- 004460	12/23/2016	2	Break Room	In staff lounge	FT-102016-004460-A	< 1	FT-102016-004460-B	< 1
2	KIMBALL ELEMENTARY SCHOOL	WS- 002465	12/23/2016	1	Bathroom	In girls' restroom adjacent to room 104 Right	FT-122016-002465-A	< 1	FT-122016-002465-B	< 1
3	KIMBALL ELEMENTARY SCHOOL	WS- 002462	12/23/2016	1	Bathroom	In boys' restroom adjacent to room 104 Left	FT-122016-002462-A	< 1	FT-122016-002462-B	< 1
4	KIMBALL ELEMENTARY SCHOOL	WS- 002464	12/23/2016	1	Bathroom	In girls' restroom adjacent to room 104 Left	FT-122016-002464-A	< 1	FT-122016-002464-B	< 1
5	KIMBALL ELEMENTARY SCHOOL	WS- 002466	12/23/2016	1	Bathroom	In classroom 102 in bathroom	FT-122016-002466-A	< 1	FT-122016-002466-B	< 1
6	KIMBALL ELEMENTARY SCHOOL	WS- 002463	12/23/2016	1	Bathroom	In boys' restroom adjacent to room 104 Right	FT-122016-002463-A	< 1	FT-122016-002463-B	< 1

Note :
Filter re-tests are only performed to devices that have sampling results greater than 1 ppb