



King Greenleaf RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012000	4/30/2018	4/30/2019	Ground Floor	Cooler	In hallway adjacent to janitors' closet	Low	Left	WF-04302018-012000	3/6/2019	FT-FY19-022019-012000-A	<1	FT-FY19-022019-012000-B	<1
WS- 012001	4/30/2018	4/30/2019	Ground Floor	Cooler	In hallway adjacent to janitors' closet	High	Right	WF-04302018-012001	3/6/2019	FT-FY19-022019-012001-A	<1	FT-FY19-022019-012001-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012002	4/30/2018	4/30/2019	Ground Floor	Food Prep Sink	In kitchen			WF-04302018-012002	3/6/2019	FT-FY19-022019-012002-A	<1	FT-FY19-022019-012002-B	<1