



King Greenleaf RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 012000	4/4/2019	4/4/2020	Ground Floor	Cooler	In hallway adjacent to janitors' closet	Low	Left	WF-04042019-012000	3/3/2020	FT-FY20-012020-012000-A	<1	FT-FY20-012020-012000-B	<1
WS- 012001	4/4/2019	4/4/2020	Ground Floor	Cooler	In hallway adjacent to janitors' closet	High	Right	WF-04042019-012001	3/3/2020	FT-FY20-012020-012001-A	<1	FT-FY20-012020-012001-B	<1
WS- 012002	4/4/2019	4/4/2020	Ground Floor	Food Prep Sink	In kitchen			WF-04042019-012002	3/3/2020	FT-FY20-012020-012002-A	<1	FT-FY20-012020-012002-B	<1