

## King Greenleaf Recreation Center Lead in Water Test Results

FY24 Filter Test

| Less than 5ppb - Devices requiring no remediation |                             |                              |              |                |  |       |                     |                  |                           |  |                           |  |
|---|-----------------------------|------------------------------|--------------|----------------|--|-------|---------------------|------------------|---------------------------|--|---------------------------|--|
| Record ID   | Filter<br>Installed<br>Date | Filter<br>Expiration<br>Date | Floor        | Device Type    | Device Location                              |       | Water Filter's Name | Date<br>Analyzed | 1st Draw - Sample ID      | FT Final<br>Result - 1st<br>Draw (ppb) | 2nd Draw - Sample ID      | FT Final<br>Result - 2nd<br>Draw (ppb) |
| WS- 012000  | 4/22/2024                   | 4/22/2025                    | Ground Floor | Cooler         | In hallway adjacent to janitors' closet Low  | Left  | WF-04222024-012000  | 5/10/2024        | FT-FY24-04242024-012000-A | <1                                     | FT-FY24-04242024-012000-B | <1                                     |
| WS- 012001  | 4/22/2024                   | 4/22/2025                    | Ground Floor | Cooler         | In hallway adjacent to janitors' closet High | Right | WF-04222024-012001  | 5/10/2024        | FT-FY24-04242024-012001-A | <1                                     | FT-FY24-04242024-012001-B | <1                                     |
| WS- 012002  | 12/6/2023                   | 12/6/2024                    | Ground Floor | Food Prep Sink | In kitchen                                   |       | WF-12062023-012002  | 5/10/2024        | FT-FY24-04242024-012002-A | <1                                     | FT-FY24-04242024-012002-B | <1                                     |