



KING GREENLEAF REC LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 011999	Bathroom	Ground Floor	In men's restroom (water source)	WT-042916-12016- A	< 2	WT-042916-12016- B	< 2				
2 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012000	Cooler	Ground Floor	In hallway adjacent to janitors closet Left Low	WT-042916-12017- A	< 2	WT-042916-12017- B	< 2				
3 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012001	Cooler	Ground Floor	In hallway adjacent to janitors closet Right High	WT-042916-12018- A	< 2	WT-042916-12018- B	< 2				
4 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012002	Kitchen	Ground Floor	In kitchen	WT-042916-12019- A	< 2	WT-042916-12019- B	< 2				
5 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012003	Classroom	Ground Floor	In art room	WT-042916-12020- A	< 2	WT-042916-12020- B	< 2				
6 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012004	Cooler	Ground Floor	Exterior (adjacent to tennis court) Left Low	WT-042916-12021- A	< 1	WT-042916-12021- B	< 2				
7 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012005	Cooler	Ground Floor	Exterior (adjacent to tennis court) Right High	WT-042916-12022- A	< 2	WT-042916-12022- B	< 2				
8 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012006	Cooler	Ground Floor	Exterior (adjacent to playground) Left Low	WT-042916-12023- A	< 2	WT-042916-12023- B	< 2				
9 KING GREENLEAF RECREATION CENTER	5/20/2016	WS- 012007	Cooler	Ground Floor	Exterior (adjacent to play ground) Right High	WT-042916-12024- A	< 2	WT-042916-12024- B	< 2				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.