



King Greenleaf Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

| RECORD ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|--------------|-------------|--|--------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 012000 | 6/16/17 | 6/16/18 | Ground Floor | Cooler | In hallway adjacent to janitors' closet Left Low | WF-62017-012000 | 2/15/18 | FT-FY18--62017-012000-A | 1.1 | FT-FY18--62017-012000-B | <1 |

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

| RECORD ID | Filter Installed Date | Filter Expiration Date | Floor | Device Type | Device Location | WATER FILTERS Name | Date Analyzed | 1st Draw - Sample ID | FT Final Result - 1st Draw (ppb) | 2nd Draw - Sample ID | FT Final Result - 2nd Draw (ppb) |
|------------|-----------------------|------------------------|--------------|----------------|-----------------|--------------------|---------------|-------------------------|----------------------------------|-------------------------|----------------------------------|
| WS- 012002 | 6/16/17 | 6/16/18 | Ground Floor | Food Prep Sink | In kitchen | WF-62017-012002 | 2/15/18 | FT-FY18--62017-012002-A | <1 | FT-FY18--62017-012002-B | <1 |