



# Kramer MS Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004414	4/2/2019	4/2/2020	Basement	Cooler	In hallway adjacent to room 003	High Left	WF-04022019-004414	1/2/2020	FT-FY20-122019-004414-A	<1	FT-FY20-122019-004414-B	<1
WS- 004415	4/2/2019	4/2/2020	Basement	Cooler	In hallway adjacent to room 003	Low Right	WF-04022019-004415	1/2/2020	FT-FY20-122019-004415-A	<1	FT-FY20-122019-004415-B	<1
WS- 004426	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 104	High Left	WF-04022019-004426	1/2/2020	FT-FY20-122019-004426-A	<1	FT-FY20-122019-004426-B	<1
WS- 004427	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 104	Low Right	WF-04022019-004427	1/2/2020	FT-FY20-122019-004427-A	<1	FT-FY20-122019-004427-B	<1
WS- 004428	4/2/2019	4/2/2020	1	Health Suite	In health suite in treatment room 110A		WF-04022019-004428	1/2/2020	FT-FY20-122019-004428-A	<1	FT-FY20-122019-004428-B	<1
WS- 004431	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 128	High Left	WF-04022019-004431	1/2/2020	FT-FY20-122019-004431-A	<1	FT-FY20-122019-004431-B	<1
WS- 004432	4/2/2019	4/2/2020	1	Cooler	In hallway adjacent to room 128	Low Right	WF-04022019-004432	1/2/2020	FT-FY20-122019-004432-A	<1	FT-FY20-122019-004432-B	<1
WS- 004433	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 200	High Left	WF-04022019-004433	1/2/2020	FT-FY20-122019-004433-A	<1	FT-FY20-122019-004433-B	<1
WS- 004434	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 200	Low Right	WF-04022019-004434	1/2/2020	FT-FY20-122019-004434-A	<1	FT-FY20-122019-004434-B	<1
WS- 004436	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 204	High Left	WF-04022019-004436	1/2/2020	FT-FY20-122019-004436-A	<1	FT-FY20-122019-004436-B	<1
WS- 004437	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 204	Low Right	WF-04022019-004437	1/2/2020	FT-FY20-122019-004437-A	<1	FT-FY20-122019-004437-B	<1
WS- 004439	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 211	High Left	WF-04022019-004439	1/2/2020	FT-FY20-122019-004439-A	<1	FT-FY20-122019-004439-B	<1
WS- 004440	4/2/2019	4/2/2020	2	Cooler	In hallway adjacent to room 211	Low Right	WF-04022019-004440	1/2/2020	FT-FY20-122019-004440-A	<1	FT-FY20-122019-004440-B	<1
WS- 008987	4/2/2019	4/2/2020	2	Break Room	In staff lounge 218		WF-04022019-008987	1/2/2020	FT-FY20-122019-008987-A	<1	FT-FY20-122019-008987-B	<1
WS- 008988	4/2/2019	4/2/2020	3	Cooler	In hallway adjacent to room 300	High Left	WF-04022019-008988	1/2/2020	FT-FY20-122019-008988-A	<1	FT-FY20-122019-008988-B	<1
WS- 008989	4/2/2019	4/2/2020	3	Cooler	In hallway adjacent to room 300	Low Right	WF-04022019-008989	1/2/2020	FT-FY20-122019-008989-A	<1	FT-FY20-122019-008989-B	<1
WS- 009001	4/2/2019	4/2/2020	3	Break Room	In break room 316		WF-04022019-009001	1/2/2020	FT-FY20-122019-009001-A	<1	FT-FY20-122019-009001-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004418	7/11/2019	7/11/2020	Basement	Food Prep Sink	In kitchen first clockwise from entry door		WF-07112019-004418	1/2/2020	FT-FY20-122019-004418-A	<1	FT-FY20-122019-004418-B	<1
WS- 004419	7/11/2019	7/11/2020	Basement	Food Prep Sink	In kitchen second clockwise from entry door		WF-07112019-004419	1/2/2020	FT-FY20-122019-004419-A	<1	FT-FY20-122019-004419-B	<1
WS- 004420	7/11/2019	7/11/2020	Basement	Food Prep Sink	In kitchen third clockwise from entry door		WF-07112019-004420	1/2/2020	FT-FY20-122019-004420-A	<1	FT-FY20-122019-004420-B	<1