



# Kramer MS Lead Water Test Results



## FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004414	4/10/2018	4/10/2019	Basement	Cooler	In hallway adjacent to room 003	High	Left	WF-04102018-004414	12/19/2018	FT-FY19-122018-004414-A	<1	FT-FY19-122018-004414-B	<1
WS- 004415	4/10/2018	4/10/2019	Basement	Cooler	In hallway adjacent to room 003	Low	Right	WF-04102018-004415	12/19/2018	FT-FY19-122018-004415-A	<1	FT-FY19-122018-004415-B	<1
WS- 004426	4/10/2018	4/10/2019	1	Cooler	In hallway adjacent to room 104	High	Left	WF-04102018-004426	12/19/2018	FT-FY19-122018-004426-A	<1	FT-FY19-122018-004426-B	<1
WS- 004427	4/10/2018	4/10/2019	1	Cooler	In hallway adjacent to room 104	Low	Right	WF-04102018-004427	12/19/2018	FT-FY19-122018-004427-A	<1	FT-FY19-122018-004427-B	<1
WS- 004428	4/10/2018	4/10/2019	1	Health Suite	In health suite in treatment room 110A			WF-04102018-004428	12/19/2018	FT-FY19-122018-004428-A	1.1	FT-FY19-122018-004428-B	<1
WS- 004431	4/10/2018	4/10/2019	1	Cooler	In hallway adjacent to room 128	High	Left	WF-04102018-004431	12/19/2018	FT-FY19-122018-004431-A	<1	FT-FY19-122018-004431-B	<1
WS- 004432	4/10/2018	4/10/2019	1	Cooler	In hallway adjacent to room 128	Low	Right	WF-04102018-004432	12/19/2018	FT-FY19-122018-004432-A	<1	FT-FY19-122018-004432-B	<1
WS- 004433	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 200	High	Left	WF-04102018-004433	12/19/2018	FT-FY19-122018-004433-A	<1	FT-FY19-122018-004433-B	<1
WS- 004434	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 200	Low	Right	WF-04102018-004434	12/19/2018	FT-FY19-122018-004434-A	<1	FT-FY19-122018-004434-B	<1
WS- 004436	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 204	High	Left	WF-04102018-004436	12/19/2018	FT-FY19-122018-004436-A	<1	FT-FY19-122018-004436-B	<1
WS- 004437	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 204	Low	Right	WF-04102018-004437	12/19/2018	FT-FY19-122018-004437-A	<1	FT-FY19-122018-004437-B	<1
WS- 004439	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 211	High	Left	WF-04102018-004439	12/19/2018	FT-FY19-122018-004439-A	<1	FT-FY19-122018-004439-B	<1
WS- 004440	4/10/2018	4/10/2019	2	Cooler	In hallway adjacent to room 211	Low	Right	WF-04102018-004440	12/19/2018	FT-FY19-122018-004440-A	<1	FT-FY19-122018-004440-B	<1
WS- 008987	4/10/2018	4/10/2019	2	Break Room	In staff lounge 218			WF-04102018-008987	12/19/2018	FT-FY19-122018-008987-A	<1	FT-FY19-122018-008987-B	<1
WS- 008999	4/10/2018	4/10/2019	3	Cooler	In hallway across from room 311	High	Left	WF-04102018-008999	12/19/2018	FT-FY19-122018-008999-A	<1	FT-FY19-122018-008999-B	<1
WS- 009000	4/10/2018	4/10/2019	3	Cooler	In hallway across from room 311	Low	Right	WF-04102018-009000	12/19/2018	FT-FY19-122018-009000-A	<1	FT-FY19-122018-009000-B	<1
WS- 009001	4/10/2018	4/10/2019	3	Break Room	In break room 316			WF-04102018-009001	12/19/2018	FT-FY19-122018-009001-A	<1	FT-FY19-122018-009001-B	<1

## Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 004418	Basement	Food Prep Sink	In kitchen first clockwise from entry door	12/19/2018	FT-FY19-122018-004418-A	<1	FT-FY19-122018-004418-B	<1