



LAMOND REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	LAMOND RECREATION CENTER	5/20/2016	WS- 005368	Utility	1	In room 132 mechanical room (water source)	WT-042916-5385- A	132	WT-042916-5385- B	14.6	Non-drinking water source - Not accessible to children			
2	LAMOND RECREATION CENTER	5/20/2016	WS- 005369	Kitchen	1	In room 129 (kitchen)	WT-042916-5386- A	< 2	WT-042916-5386- B	< 2				
3	LAMOND RECREATION CENTER	5/20/2016	WS- 005370	Fountain	1	In room 131 fitness center	WT-042916-5387- A	< 2	WT-042916-5387- B	< 2				
4	LAMOND RECREATION CENTER	5/20/2016	WS- 005371	Fountain	1	In room 131 fitness center	WT-042916-5388- A	< 2	WT-042916-5388- B	< 2				
5	LAMOND RECREATION CENTER	5/20/2016	WS- 005372	Fountain	1	in hallway adjacent to room 107	WT-042916-5389- A	< 2	WT-042916-5389- B	< 2				
6	LAMOND RECREATION CENTER	5/20/2016	WS- 005373	Fountain	1	in hallway adjacent to room 107	WT-042916-5390- A	< 2	WT-042916-5390- B	< 2				
7	LAMOND RECREATION CENTER	5/20/2016	WS- 005374	Classroom	1	In room 108 arts & crafts	WT-042916-5391- A	< 2	WT-042916-5391- B	< 2				
8	LAMOND RECREATION CENTER	5/20/2016	WS- 005375	Fountain	1	in hallway adjacent to room 128	WT-042916-5392- A	< 2	WT-042916-5392- B	< 2				
9	LAMOND RECREATION CENTER	5/20/2016	WS- 005376	Fountain	1	In hallway adjacent to room 128	WT-042916-5393- A	< 2	WT-042916-5393- B	< 2				
10	LAMOND RECREATION CENTER	5/20/2016	WS- 005377	Fountain	Ground Floor	Exterior adjacent to work out room	WT-042916-5394- A	< 2	WT-042916-5394- B	< 2				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.