



LANGDON LEAD WATER TEST RESULTS

May 15, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw	
1	LANGDON EC	5/7/2016	WS-009114	Classroom	1	In health suit room 004	WT-042916-9131-A	< 1	WT-042916-9131-B	4.17				
2	LANGDON EC	5/7/2016	WS-009113	Cooler	1	In auditorium	WT-042916-9130-A	< 1	WT-042916-9130-B	< 1				
3	LANGDON EC	5/7/2016	WS-009112	Classroom	2	In classroom 213	Right	WT-042916-9129-A	< 1	WT-042916-9129-B	< 1			
4	LANGDON EC	5/7/2016	WS-009111	Classroom	2	In classroom 213	Left	WT-042916-9128-A	< 1	WT-042916-9128-B	1.27			
5	LANGDON EC	5/7/2016	WS-009110	Fountain	2	In hallway across from room 212	Right Low	WT-042916-9127-A	< 1	WT-042916-9127-B	< 1			
6	LANGDON EC	5/7/2016	WS-009109	Fountain	2	In hallway across from room 212	Left High	WT-042916-9126-A	< 1	WT-042916-9126-B	< 1			
7	LANGDON EC	5/7/2016	WS-009108	Fountain	2	In hallway adjacent to room 204	Right Low	WT-042916-9125-A	1.17	WT-042916-9125-B	< 1			
8	LANGDON EC	5/7/2016	WS-009107	Fountain	2	In hallway adjacent to room 204	Left High	WT-042916-9124-A	< 1	WT-042916-9124-B	1.04			
9	LANGDON EC	5/7/2016	WS-009106	Classroom	2	In classroom 209	Right	WT-042916-9123-A	< 1	WT-042916-9123-B	< 1			
10	LANGDON EC	5/7/2016	WS-009105	Classroom	2	In classroom 247 west wall	Right	WT-042916-9122-A	1.03	WT-042916-9122-B	5.01			
11	LANGDON EC	5/7/2016	WS-009104	Classroom	2	In classroom 247 west wall	Mid	WT-042916-9121-A	1.48	WT-042916-9121-B	6.04			
12	LANGDON EC	5/7/2016	WS-009103	Classroom	1	In classroom 247 west wall	Left	WT-042916-9120-A	2.47	WT-042916-9120-B	7.73			
13	LANGDON EC	5/7/2016	WS-009102	Fountain	2	In classroom 247 south wall	Right	WT-042916-9119-A	1.78	WT-042916-9119-B	2.45			
14	LANGDON EC	5/7/2016	WS-009101	Classroom	2	In classroom 247 south wall	Mid Low	WT-042916-9118-A	2.12	WT-042916-9118-B	2.37			
15	LANGDON EC	5/7/2016	WS-009100	Classroom	2	In classroom 247 south wall	Left High	WT-042916-9117-A	1.42	WT-042916-9117-B	2			
16	LANGDON EC	5/7/2016	WS-009099	Classroom	2	In teachers work room 254	Right	WT-042916-9116-A	< 1	WT-042916-9116-B	< 1			
17	LANGDON EC	5/7/2016	WS-009098	Fountain	2	In hallway across from room 254	Right Low	WT-042916-9115-A	< 1	WT-042916-9115-B	< 1			
18	LANGDON EC	5/7/2016	WS-009097	Fountain	2	In hallway across from room 254	Left High	WT-042916-9114-A	< 1	WT-042916-9114-B	< 1			
19	LANGDON EC	5/7/2016	WS-009096	Classroom	1	In teachers work room 154	Right	WT-042916-9113-A	< 1	WT-042916-9113-B	1.67			
20	LANGDON EC	5/7/2016	WS-009095	Fountain	1	In hallway across from room 154	Right Low	WT-042916-9112-A	< 1	WT-042916-9112-B	< 1			
21	LANGDON EC	5/7/2016	WS-009094	Classroom	1	In hallway across from room 154	Left High	WT-042916-9111-A	< 1	WT-042916-9111-B	< 1			
22	LANGDON EC	5/7/2016	WS-009093	Classroom	1	In room 002	Right	WT-042916-9110-A	2.03	WT-042916-9110-B	< 1			
23	LANGDON EC	5/7/2016	WS-009092	Classroom	1	In resource room 103	Right Low	WT-042916-9109-A	4.7	WT-042916-9109-B	< 1			
24	LANGDON EC	5/7/2016	WS-009091	Classroom	1	In resource room 103	Mid Low	WT-042916-9108-A	11.1	WT-042916-9108-B	1.99			
25	LANGDON EC	5/7/2016	WS-009090	Classroom	1	In resource room	Left High	WT-042916-9107-A	1.44	WT-042916-9107-B	< 1			
26	LANGDON EC	5/7/2016	WS-009089	Classroom	1	In classroom 110	Right High	WT-042916-9106-A	4.57	WT-042916-9106-B	5.04			
27	LANGDON EC	5/7/2016	WS-009088	Fountain	1	In classroom 110	Mid Low	WT-042916-9105-A	3.22	WT-042916-9105-B	< 1			
28	LANGDON EC	5/7/2016	WS-009087	Classroom	1	In classroom 110	Left Low	WT-042916-9104-A	3.62	WT-042916-9104-B	1.24			
29	LANGDON EC	5/7/2016	WS-009086	Classroom	1	In classroom 109	Right High	WT-042916-9103-A	< 1	WT-042916-9103-B	< 1			
30	LANGDON EC	5/7/2016	WS-009085	Classroom	1	In classroom 109	Mid Low	WT-042916-9102-A	7.87	WT-042916-9102-B	< 1			
31	LANGDON EC	5/7/2016	WS-009084	Classroom	1	In classroom 109	Left Low	WT-042916-9101-A	< 1	WT-042916-9101-B	< 1			
32	LANGDON EC	5/7/2016	WS-009083	Classroom	1	In classroom 108	Right High	WT-042916-9100-A	6.48	WT-042916-9100-B	< 1			
33	LANGDON EC	5/7/2016	WS-009082	Fountain	1	In classroom 108	Mid Low	WT-042916-9099-A	< 1	WT-042916-9099-B	5.68			
34	LANGDON EC	5/7/2016	WS-009081	Classroom	1	In classroom 108	Left Low	WT-042916-9098-A	4.49	WT-042916-9098-B	< 1			
35	LANGDON EC	5/7/2016	WS-009080	Classroom	1	In classroom 107	Right Low	WT-042916-9097-A	1.83	WT-042916-9097-B	< 1			
36	LANGDON EC	5/7/2016	WS-009079	Fountain	1	In classroom 107	Mid Low	WT-042916-9096-A	< 1	WT-042916-9096-B	1.35			
37	LANGDON EC	5/7/2016	WS-009078	Classroom	1	In classroom 107	Left High	WT-042916-9095-A	1.99	WT-042916-9095-B	< 1			
38	LANGDON EC	5/7/2016	WS-009077	Fountain	1	In hallway across from room 105	Right Low	WT-042916-9094-A	2.04	WT-042916-9094-B	< 1			
39	LANGDON EC	5/7/2016	WS-009076	Fountain	1	In hallway across from room 105	Left High	WT-042916-9093-A	< 1	WT-042916-9093-B	< 1			
40	LANGDON EC	5/7/2016	WS-009075	Classroom	1	In classroom 106	Right Low	WT-042916-9092-A	< 1	WT-042916-9092-B	< 1			
41	LANGDON EC	5/7/2016	WS-009074	Fountain	1	In classroom 106	Mid Low	WT-042916-9091-A	1.84	WT-042916-9091-B	< 1			
42	LANGDON EC	5/7/2016	WS-009073	Classroom	1	In classroom 106	Left High	WT-042916-9090-A	< 1	WT-042916-9090-B	2.05			
43	LANGDON EC	5/7/2016	WS-009072	Classroom	1	In classroom 104	Right High	WT-042916-9089-A	< 1	WT-042916-9089-B	< 1			
44	LANGDON EC	5/7/2016	WS-009071	Fountain	1	In classroom 104	Mid Low	WT-042916-9088-A	< 1	WT-042916-9088-B	< 1			
45	LANGDON EC	5/7/2016	WS-009070	Classroom	1	In classroom 104	Left Low	WT-042916-9087-A	< 1	WT-042916-9087-B	< 1			
46	LANGDON EC	5/7/2016	WS-009069	Fountain	1	In hallway adjacent to room 104	Right Low	WT-042916-9086-A	1.75	WT-042916-9086-B	1.93			
47	LANGDON EC	5/7/2016	WS-009068	Fountain	1	In hallway adjacent to room 104	Left High	WT-042916-9085-A	< 1	WT-042916-9085-B	1.36			
48	LANGDON EC	5/7/2016	WS-009067	Classroom	1	In teachers work room 113	Right	WT-042916-9084-A	1.13	WT-042916-9084-B	< 1			
49	LANGDON EC	5/7/2016	WS-009066	Classroom	1	In classroom 102	Right Low	WT-042916-9083-A	< 1	WT-042916-9083-B	< 1			
50	LANGDON EC	5/7/2016	WS-009065	Classroom	1	In classroom 102	Mid Low	WT-042916-9082-A	< 1	WT-042916-9082-B	2.43			
51	LANGDON EC	5/7/2016	WS-009064	Classroom	1	In classroom 102	Right High	WT-042916-9081-A	< 1	WT-042916-9081-B	< 1			
52	LANGDON EC	5/7/2016	WS-009063	Classroom	1	In classroom 101	Right High	WT-042916-9080-A	3.05	WT-042916-9080-B	< 1			
53	LANGDON EC	5/7/2016	WS-009062	Fountain	1	In classroom 101	Mid Low	WT-042916-9079-A	< 1	WT-042916-9079-B	< 1			
54	LANGDON EC	5/7/2016	WS-009061	Classroom	1	In classroom 101	Left Low	WT-042916-9078-A	< 1	WT-042916-9078-B	< 1			
55	LANGDON EC	5/7/2016	WS-009060	Kitchen	Basement	In kitchen (shower head)	Right	WT-042916-9077-A	6.71	WT-042916-9077-B	5.81			
56	LANGDON EC	5/7/2016	WS-009059	Kitchen	Basement	In kitchen south wall	Right	WT-042916-9076-A	< 1	WT-042916-9076-B	< 1			
57	LANGDON EC	5/7/2016	WS-009058	Utility	Basement	In boiler room	Right	WT-042916-9075-A	25.2	WT-042916-9075-B	19.1	Non-drinking Water Source - Not Accessible to Children		

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.