



LANGDON EC LEAD WATER TEST RESULTS



Initial Filter Test After Installation

Less than 1 ppb - Device Returned to Service												
	Building Location: Building Name	Water Source ID	Date Analyzed	Floor	Device Type	Device Location			1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	LANGDON EDUCATIONAL CAMPUS	WS- 009099	1/7/2017	2	Break Room	In staff work room 254			FT-102016-009099-A	< 1	FT-102016-009099-B	< 1
2	LANGDON EDUCATIONAL CAMPUS	WS- 009067	1/7/2017	1	Break Room	In staff work room 113			FT-102016-009067-A	< 1	FT-102016-009067-B	< 1
3	LANGDON EDUCATIONAL CAMPUS	WS- 009096	1/7/2017	1	Break Room	In staff work room 154			FT-102016-009096-A	< 1	FT-102016-009096-B	< 1
4	LANGDON EDUCATIONAL CAMPUS	WS- 009075	1/7/2017	1	Classroom Faucet	In classroom 106	Low	Right	FT-112016-009075-A	< 1	FT-112016-009075-B	< 1
5	LANGDON EDUCATIONAL CAMPUS	WS- 009092	1/7/2017	1	Classroom Faucet	In resource room 103	Low	Right	FT-112016-009092-A	< 1	FT-112016-009092-B	< 1
6	LANGDON EDUCATIONAL CAMPUS	WS- 009090	1/7/2017	1	Classroom Faucet	In resource room 103	High	Left	FT-112016-009090-A	< 1	FT-112016-009090-B	< 1
7	LANGDON EDUCATIONAL CAMPUS	WS- 009078	1/7/2017	1	Classroom Faucet	In classroom 107	High	Left	FT-112016-009078-A	< 1	FT-112016-009078-B	< 1
8	LANGDON EDUCATIONAL CAMPUS	WS- 009089	1/7/2017	1	Classroom Faucet	In classroom 110	High	Right	FT-112016-009089-A	< 1	FT-112016-009089-B	< 1
9	LANGDON EDUCATIONAL CAMPUS	WS- 009087	1/7/2017	1	Classroom Faucet	In classroom 110	Low	Left	FT-112016-009087-A	< 1	FT-112016-009087-B	< 1
10	LANGDON EDUCATIONAL CAMPUS	WS- 009072	1/7/2017	1	Classroom Faucet	In classroom 104	High	Right	FT-112016-009072-A	< 1	FT-112016-009072-B	< 1
11	LANGDON EDUCATIONAL CAMPUS	WS- 009070	1/7/2017	1	Classroom Faucet	In classroom 104	Low	Left	FT-112016-009070-A	< 1	FT-112016-009070-B	< 1
12	LANGDON EDUCATIONAL CAMPUS	WS- 009063	1/7/2017	1	Classroom Faucet	In classroom 101	High	Right	FT-112016-009063-A	< 1	FT-112016-009063-B	< 1
13	LANGDON EDUCATIONAL CAMPUS	WS- 009066	1/7/2017	1	Classroom Faucet	In classroom 102	Low	Right	FT-112016-009066-A	< 1	FT-112016-009066-B	< 1
14	LANGDON EDUCATIONAL CAMPUS	WS- 009064	1/7/2017	1	Classroom Faucet	In classroom 102	High	Left	FT-112016-009064-A	< 1	FT-112016-009064-B	< 1
15	LANGDON EDUCATIONAL CAMPUS	WS- 009061	1/7/2017	1	Classroom Faucet	In classroom 101	Low	Left	FT-112016-009061-A	< 1	FT-112016-009061-B	< 1

Greater than 1 ppb - Devices Shut Off and Corrective Action Taken												
1	LANGDON EDUCATIONAL CAMPUS	WS- 009081	1/7/2017	1	Classroom Faucet	In classroom 108	Low	Left	FT-112016-009081-A	1.3	FT-112016-009081-B	< 1
2	LANGDON EDUCATIONAL CAMPUS	WS- 009073	1/7/2017	1	Classroom Faucet	In classroom 106	High	Left	FT-112016-009073-A	1.1	FT-112016-009073-B	< 1
3	LANGDON EDUCATIONAL CAMPUS	WS- 009084	1/7/2017	1	Classroom Faucet	In classroom 109	Low	Left	FT-112016-009084-A	1.5	FT-112016-009084-B	< 1
4	LANGDON EDUCATIONAL CAMPUS	WS- 009080	1/7/2017	1	Classroom Faucet	In classroom 107	Low	Right	FT-112016-009080-A	1.1	FT-112016-009080-B	< 1
5	LANGDON EDUCATIONAL CAMPUS	WS- 009083	1/7/2017	1	Classroom Faucet	In classroom 108	High	Right	FT-112016-009083-A	1.3	FT-112016-009083-B	< 1
6	LANGDON EDUCATIONAL CAMPUS	WS- 009086	1/7/2017	1	Classroom Faucet	In classroom 109	High	Right	FT-112016-009086-A	1.2	FT-112016-009086-B	< 1

First Filter Re-Test (After Filter and Plumbing Check with Aerator Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation												
1	LANGDON EDUCATIONAL CAMPUS	WS- 009081	2/8/2017	1	Classroom Faucet	In classroom 108	Low	Left	FT-112016-009081-A	4.5	FT-112016-009081-B	< 1
2	LANGDON EDUCATIONAL CAMPUS	WS- 009073	2/8/2017	1	Classroom Faucet	In classroom 106	High	Left	FT-112016-009073-A	2.8	FT-112016-009073-B	< 1
3	LANGDON EDUCATIONAL CAMPUS	WS- 009084	2/8/2017	1	Classroom Faucet	In classroom 109	Low	Left	FT-112016-009084-A	3.1	FT-112016-009084-B	< 1
4	LANGDON EDUCATIONAL CAMPUS	WS- 009080	2/8/2017	1	Classroom Faucet	In classroom 107	Low	Right	FT-112016-009080-A	4.1	FT-112016-009080-B	< 1
5	LANGDON EDUCATIONAL CAMPUS	WS- 009083	2/8/2017	1	Classroom Faucet	In classroom 108	High	Right	FT-112016-009083-A	1.7	FT-112016-009083-B	< 1
6	LANGDON EDUCATIONAL CAMPUS	WS- 009086	2/8/2017	1	Classroom Faucet	In classroom 109	High	Right	FT-112016-009086-A	2.8	FT-112016-009086-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb

Second Filter Re-Test (After Device Replacement)

Greater than 1 ppb - Devices Remain Shut off, Continued Remediation												
1	LANGDON EDUCATIONAL CAMPUS	WS- 009081	3/30/2017	1	Classroom Faucet	In classroom 108	Low	Left	FT-112016-009081-A	4.6	FT-112016-009081-B	< 1
2	LANGDON EDUCATIONAL CAMPUS	WS- 009073	3/30/2017	1	Classroom Faucet	In classroom 106	High	Left	FT-112016-009073-A	6.6	FT-112016-009073-B	< 1
3	LANGDON EDUCATIONAL CAMPUS	WS- 009084	3/30/2017	1	Classroom Faucet	In classroom 109	Low	Left	FT-112016-009084-A	8.6	FT-112016-009084-B	< 1
4	LANGDON EDUCATIONAL CAMPUS	WS- 009080	3/30/2017	1	Classroom Faucet	In classroom 107	Low	Right	FT-112016-009080-A	4.2	FT-112016-009080-B	< 1
5	LANGDON EDUCATIONAL CAMPUS	WS- 009083	3/30/2017	1	Classroom Faucet	In classroom 108	High	Right	FT-112016-009083-A	4	FT-112016-009083-B	< 1
6	LANGDON EDUCATIONAL CAMPUS	WS- 009086	3/30/2017	1	Classroom Faucet	In classroom 109	High	Right	FT-112016-009086-A	3.4	FT-112016-009086-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb