



# Langdon Park Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005790	3/13/2024	3/13/2025	1	Cooler	In hallway adjacent to reception	WF-03132024-005790	4/1/2024	FT-FY24-03202024-005790-A	<1	FT-FY24-03202024-005790-B	<1
WS- 005791	3/13/2024	3/13/2025	1	Cooler	In hallway adjacent to room 206	WF-03132024-005791	4/1/2024	FT-FY24-03202024-005791-A	<1	FT-FY24-03202024-005791-B	<1
WS- 005792	11/29/2023	11/29/2024	1	Food Prep Sink	In kitchen 212	WF-11292023-005792	4/1/2024	FT-FY24-03202024-005792-A	<1	FT-FY24-03202024-005792-B	<1
WS- 005793	3/13/2024	3/13/2025	Basement	Cooler	In hallway adjacent to gym 115	WF-03132024-005793	4/1/2024	FT-FY24-03202024-005793-A	<1	FT-FY24-03202024-005793-B	<1