



Langdon Park RC Lead Water Test Results



FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-005793	6/17/17	6/17/18	Basement	Cooler	In hallway adjacent to gym 115	WF-62017-005793	2/6/18	FT-FY18--62017-005793-A	<1	FT-FY18--62017-005793-B	<1

Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-005792	6/19/17	6/19/18	1	Food Prep Sink	In kitchen 212	WF-62017-005792	2/6/18	FT-FY18--62017-005792-A	<1	FT-FY18--62017-005792-B	<1