



Langdon Park RC Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005790	5/2/2018	5/2/2019	1	Cooler	In hallway adjacent to reception	WF-05022018-005790	2/25/2019	FT-FY19-022019-005790-A	<1	FT-FY19-022019-005790-B	<1
WS- 005791	5/2/2018	5/2/2019	1	Cooler	In hallway adjacent to room 206	WF-05022018-005791	2/25/2019	FT-FY19-022019-005791-A	<1	FT-FY19-022019-005791-B	<1
WS- 005793	5/2/2018	5/2/2019	Basement	Cooler	In hallway adjacent to gym 115	WF-05022018-005793	2/25/2019	FT-FY19-022019-005793-A	<1	FT-FY19-022019-005793-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005792	5/15/2018	5/15/2019	1	Food Prep Sink	In kitchen 212	WF-05152018-005792	2/25/2019	FT-FY19-022019-005792-A	<1	FT-FY19-022019-005792-B	<1