



Langdon Park RC Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 005790	4/11/2019	4/11/2020	1	Cooler	In hallway adjacent to reception	WF-04112019-005790	2/26/2020	FT-FY20-012020-005790-A	<1	FT-FY20-012020-005790-B	<1
WS- 005791	4/11/2019	4/11/2020	1	Cooler	In hallway adjacent to room 206	WF-04112019-005791	2/26/2020	FT-FY20-012020-005791-A	<1	FT-FY20-012020-005791-B	<1
WS- 005792	4/11/2019	4/11/2020	1	Food Prep Sink	In kitchen 212	WF-04112019-005792	2/26/2020	FT-FY20-012020-005792-A	<1	FT-FY20-012020-005792-B	<1
WS- 005793	4/11/2019	4/11/2020	Basement	Cooler	In hallway adjacent to gym 115	WF-04112019-005793	2/26/2020	FT-FY20-012020-005793-A	<1	FT-FY20-012020-005793-B	<1