

## **Langdon Park Recreation Center Lead in Water Test Results**

## **FY23 Filter Test**

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 005790	3/31/2022	3/31/2023	1	Cooler	In hallway adjacent to reception	WF-03312022-005790	2/20/2023	FT-FY23-02022023-005790-A	<1	FT-FY23-02022023-005790-B	<1	
WS- 005791	3/31/2022	3/31/2023	1	Cooler	In hallway adjacent to room 206	WF-03312022-005791	2/20/2023	FT-FY23-02022023-005791-A	<1	FT-FY23-02022023-005791-B	<1	
WS- 005792	1/4/2023	1/4/2024	1	Food Prep Sink	In kitchen 212	WF-01042023-005792	2/20/2023	FT-FY23-02022023-005792-A	<1	FT-FY23-02022023-005792-B	<1	
WS- 005793	3/31/2022	3/31/2023	Basement	Cooler	In hallway adjacent to gym 115	WF-03312022-005793	2/20/2023	FT-FY23-02022023-005793-A	<1	FT-FY23-02022023-005793-B	<1	