



LANGDON PARK REC LEAD WATER TEST RESULTS May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005789	Bathroom	Basement	In men's locker room Right	WT-042916-5806- A	18	WT-042916-5806- B	4.6	Filter will be installed and then retested			
2 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005790	Cooler	1	In hallway adjacent to reception	WT-042916-5807- A	< 1	WT-042916-5807- B	< 1				
3 LANGDON PARK RECREATION CENTER	5/19/2016	WS- 005791	Cooler	1	In hallway adjacent to room 206 multipurpose room	WT-042916-5808- A	< 1	WT-042916-5808- B	< 1				
4 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005792	Kitchen	1	In kitchen 212	WT-042916-5809- A	< 1	WT-042916-5809- B	< 1				
5 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005793	Cooler	Basement	In hallway adjacent to gymnasium 115	WT-042916-5810- A	< 1	WT-042916-5810- B	< 1				
6 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005794	Fountain	Ground Floor	Exterior adjacent to outdoor basketball court Left Low	WT-042916-5811- A	< 1	WT-042916-5811- B	< 1				
7 LANGDON PARK RECREATION CENTER	5/26/2016	WS- 005795	Cooler	Ground Floor	Exterior adjacent to outdoor basketball court Right High	WT-042916-5812- A	< 1	WT-042916-5812- B	< 1				
8 LANGDON PARK POOL & BATH HOUSE	5/26/2016	WS- 005796	Fountain	Ground Floor	Exterior adjacent to men's locker room	WT-042916-5813- A	13	WT-042916-5813- B	1.8				
9 LANGDON PARK POOL & BATH HOUSE	5/26/2016	WS- 005797	Fountain	Ground Floor	Exterior adjacent to women's locker room	WT-042916-5814- A	7.9	WT-042916-5814- B	4				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.