



LANGDON PARK REC LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	LANGDON PARK RECREATION CENTER	WS- 005790	9/22/2016	1	Cooler	In hallway adjacent to reception	FT-82016-005790-A	< 1	FT-82016-005790-B	< 1
2	LANGDON PARK RECREATION CENTER	WS- 005791	9/22/2016	1	Cooler	In hallway adjacent to room 206	FT-82016-005791-A	< 1	FT-82016-005791-B	< 1
3	LANGDON PARK RECREATION CENTER	WS- 005792	9/22/2016	1	Food Prep Sink	In kitchen 212	FT-82016-005792-A	< 1	FT-82016-005792-B	< 1
4	LANGDON PARK RECREATION CENTER	WS- 005793	9/22/2016	Basement	Cooler	In hallway adjacent to gym 115	FT-82016-005793-A	< 1	FT-82016-005793-B	< 1