



# Langdon ES Lead Water Test



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation													
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009061	10/31/2017	10/31/2018	1	Combo Faucet	In classroom 101	Left	Low	WF-102017-009061	11/21/2017	FT-FY18-102017-009061-A	2.8	FT-FY18-102017-009061-B	<1
WS-009066	10/31/2017	10/31/2018	1	Combo Faucet	In classroom 102	Right	Low	WF-102017-009066	11/21/2017	FT-FY18-102017-009066-A	3	FT-FY18-102017-009066-B	<1
WS-009067	6/15/2017	6/15/2018	1	Break Room	In staff work room 113			WF-62017-009067	11/21/2017	FT-FY18-62017-009067-A	<1	FT-FY18-62017-009067-B	<1
WS-009070	10/31/2017	10/31/2018	1	Combo Faucet	In classroom 104	Left	Low	WF-102017-009070	11/21/2017	FT-FY18-102017-009070-A	<1	FT-FY18-102017-009070-B	<1
WS-009071	6/15/2017	6/15/2018	1	Combo Fountain	In classroom 104	Mid	Low	WF-62017-009071	11/21/2017	FT-FY18-62017-009071-A	<1	FT-FY18-62017-009071-B	<1
WS-009079	6/15/2017	6/15/2018	1	Combo Fountain	In classroom 107	Mid	Low	WF-62017-009079	11/21/2017	FT-FY18-62017-009079-A	<1	FT-FY18-62017-009079-B	<1
WS-009081	10/31/2017	10/31/2018	1	Combo Faucet	In classroom 108	Left	Low	WF-102017-009081	11/21/2017	FT-FY18-102017-009081-A	<1	FT-FY18-102017-009081-B	<1
WS-009083	10/31/2017	10/31/2018	1	Classroom Faucet	In classroom 108	Right	High	WF-102017-009083	11/21/2017	FT-FY18-102017-009083-A	<1	FT-FY18-102017-009083-B	<1
WS-009084	10/31/2017	10/31/2018	1	Combo Faucet	In classroom 109	Left	Low	WF-102017-009084	11/21/2017	FT-FY18-102017-009084-A	1.2	FT-FY18-102017-009084-B	<1
WS-009085	6/15/2017	6/15/2018	1	Combo Fountain	In classroom 109	Mid	Low	WF-62017-009085	11/21/2017	FT-FY18-62017-009085-A	<1	FT-FY18-62017-009085-B	<1
WS-009086	10/31/2017	10/31/2018	1	Classroom Faucet	In classroom 109	Right	High	WF-102017-009086	11/21/2017	FT-FY18-102017-009086-A	2.2	FT-FY18-102017-009086-B	<1
WS-009091	6/15/2017	6/15/2018	1	Combo Fountain	In resource room 103	Mid	Low	WF-62017-009091	11/21/2017	FT-FY18-62017-009091-A	<1	FT-FY18-62017-009091-B	<1
WS-009098	6/15/2017	6/15/2018	2	Cooler	In hallway across from room 254	Right	Low	WF-62017-009098	11/21/2017	FT-FY18-62017-009098-A	<1	FT-FY18-62017-009098-B	<1
WS-009102	6/15/2017	6/15/2018	2	Combo Fountain	In science lab room 247 second clockwise from entry door			WF-62017-009102	11/21/2017	FT-FY18-62017-009102-A	<1	FT-FY18-62017-009102-B	<1
WS-009114	6/15/2017	6/15/2018	1	Health Suite	In health suite 004			WF-62017-009114	11/21/2017	FT-FY18-62017-009114-A	<1	FT-FY18-62017-009114-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Floor	Device Type	Device Location				Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-009059	Basement	Food Prep Sink	In kitchen				11/21/2017	FT-FY18-102017-009059-A	<1	FT-FY18-102017-009059-B	<1