



LANGLEY ES LEAD WATER TEST RESULTS



Initial Filter Test After Installation

	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	Final Result - 2nd Draw (ppb)
1	LANGLEY ELEMENTARY SCHOOL	WS- 004233	12/27/2016	1	Combo Faucet	In classroom 149	FT-122016-004233-A	< 1	FT-122016-004233-B	< 1
2	LANGLEY ELEMENTARY SCHOOL	WS- 004236	12/27/2016	1	Combo Faucet	In classroom 137	FT-122016-004236-A	< 1	FT-122016-004236-B	< 1
3	LANGLEY ELEMENTARY SCHOOL	WS- 004243	12/27/2016	1	Combo Faucet	In classroom 122	FT-122016-004243-A	< 1	FT-122016-004243-B	< 1
4	LANGLEY ELEMENTARY SCHOOL	WS- 004225	12/27/2016	1	Combo Faucet	In classroom 125	FT-122016-004225-A	< 1	FT-122016-004225-B	< 1
5	LANGLEY ELEMENTARY SCHOOL	WS- 004231	12/27/2016	1	Combo Faucet	In classroom 143	FT-122016-004231-A	< 1	FT-122016-004231-B	< 1
6	LANGLEY ELEMENTARY SCHOOL	WS- 004240	12/27/2016	1	Combo Faucet	In classroom 113	FT-122016-004240-A	< 1	FT-122016-004240-B	< 1
7	LANGLEY ELEMENTARY SCHOOL	WS- 004230	12/27/2016	1	Combo Faucet	In classroom 133	FT-122016-004230-A	< 1	FT-122016-004230-B	< 1
8	LANGLEY ELEMENTARY SCHOOL	WS- 004227	12/27/2016	1	Break Room	In staff lounge	FT-112016-004227-A	< 1	FT-112016-004227-B	< 1

Note :

Filter re-tests are only performed to devices that have sampling results greater than 1 ppb