



MLK ES Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 008504	4/9/2018	4/9/2019	1	Cooler	In gym/cafeteria	WF-04092018-008504	10/23/2018	FT-FY19-102018-008504-A	< 1	FT-FY19-102018-008504-B	< 1	
WS- 008505	4/9/2018	4/9/2019	1	Health Suite	In health suite 108	WF-04092018-008505	10/23/2018	FT-FY19-102018-008505-A	< 1	FT-FY19-102018-008505-B	< 1	
WS- 008508	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to boys' restroom	High Left	WF-04092018-008508	10/23/2018	FT-FY19-102018-008508-A	< 1	FT-FY19-102018-008508-B	< 1
WS- 008509	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to boys' restroom	Low Right	WF-04092018-008509	10/23/2018	FT-FY19-102018-008509-A	< 1	FT-FY19-102018-008509-B	< 1
WS- 008510	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to girls' restroom	High Left	WF-04092018-008510	10/23/2018	FT-FY19-102018-008510-A	< 1	FT-FY19-102018-008510-B	< 1
WS- 008511	4/9/2018	4/9/2019	1	Cooler	In hallway adjacent to girls' restroom	Low Right	WF-04092018-008511	10/23/2018	FT-FY19-102018-008511-A	< 1	FT-FY19-102018-008511-B	< 1
WS- 008521	4/9/2018	4/9/2019	2	Cooler	In hallway adjacent to room 208	High Left	WF-04092018-008521	10/23/2018	FT-FY19-102018-008521-A	< 1	FT-FY19-102018-008521-B	< 1
WS- 008522	4/9/2018	4/9/2019	2	Cooler	In hallway adjacent to room 208	Low Right	WF-04092018-008522	10/23/2018	FT-FY19-102018-008522-A	< 1	FT-FY19-102018-008522-B	< 1
WS- 008524	4/9/2018	4/9/2019	2	Cooler	In hallway adjacent to boys' restroom 206	High Left	WF-04092018-008524	10/23/2018	FT-FY19-102018-008524-A	< 1	FT-FY19-102018-008524-B	< 1
WS- 008525	4/9/2018	4/9/2019	2	Cooler	In hallway adjacent to boys' restroom 206	Low Right	WF-04092018-008525	10/23/2018	FT-FY19-102018-008525-A	< 1	FT-FY19-102018-008525-B	< 1
WS- 008534	4/9/2018	4/9/2019	3	Cooler	In hallway adjacent to room 307	High Right	WF-04092018-008534	10/23/2018	FT-FY19-102018-008534-A	< 1	FT-FY19-102018-008534-B	< 1
WS- 008535	4/9/2018	4/9/2019	3	Cooler	In hallway adjacent to room 307	Low Right	WF-04092018-008535	10/23/2018	FT-FY19-102018-008535-A	< 1	FT-FY19-102018-008535-B	< 1
WS- 008506	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 109	WF-09172018-008506	10/23/2018	FT-FY19-102018-008506-A	< 1	FT-FY19-102018-008506-B	< 1	
WS- 008507	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 118	WF-09172018-008507	10/23/2018	FT-FY19-102018-008507-A	< 1	FT-FY19-102018-008507-B	< 1	
WS- 008512	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 117	WF-09172018-008512	10/23/2018	FT-FY19-102018-008512-A	< 1	FT-FY19-102018-008512-B	< 1	
WS- 008513	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 113	WF-09172018-008513	10/23/2018	FT-FY19-102018-008513-A	< 1	FT-FY19-102018-008513-B	< 1	
WS- 008514	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 114	WF-09172018-008514	10/23/2018	FT-FY19-102018-008514-A	< 1	FT-FY19-102018-008514-B	< 1	
WS- 008515	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 116	WF-09172018-008515	10/23/2018	FT-FY19-102018-008515-A	< 1	FT-FY19-102018-008515-B	< 1	
WS- 008516	9/17/2018	9/17/2019	1	Classroom Faucet	In classroom 115	WF-09172018-008516	10/23/2018	FT-FY19-102018-008516-A	< 1	FT-FY19-102018-008516-B	< 1	

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 008502	1	Food Prep Sink	In kitchen second clockwise from entry door	10/23/2018	FT-FY19-102018-008502-A	< 1	FT-FY19-102018-008502-B	< 1
WS- 008503	1	Food Prep Sink	In kitchen third clockwise from entry door	10/23/2018	FT-FY19-102018-008503-A	< 1	FT-FY19-102018-008503-B	< 1