



Macfarland MS Lead Water Test Results



FY19 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-014050	8/9/2018	8/9/2019	Basement	Break Room	In staff lounge B-114	WF-08092018-014050	8/19/2018	FT-FY19-082018-014050-A	< 1	FT-FY19-082018-014050-B	1.6	
WS-014051	8/9/2018	8/9/2019	Basement	Health Suite	In wellness room B-113	WF-08092018-014051	8/19/2018	FT-FY19-082018-014051-A	< 1	FT-FY19-082018-014051-B	2.2	
WS-014053	8/9/2018	8/9/2019	Basement	Cooler	In hallway adjacent to B2-0246	WF-08092018-014053	8/19/2018	FT-FY19-082018-014053-A	< 1	FT-FY19-082018-014053-B	< 1	
WS-014055	8/9/2018	8/9/2019	Basement	Combo Fountain	In makerspace room B2-0311	WF-08092018-014055	8/19/2018	FT-FY19-082018-014055-A	< 1	FT-FY19-082018-014055-B	< 1	
WS-014058	8/9/2018	8/9/2019	Basement	Cooler	In hallway adjacent to B1-0244	WF-08092018-014058	8/19/2018	FT-FY19-082018-014058-A	< 1	FT-FY19-082018-014058-B	< 1	
WS-014059	8/9/2018	8/9/2019	1	Bottle Filler	In hallway adjacent to all gender restroom 1103A	WF-08092018-014059	8/19/2018	FT-FY19-082018-014059-A	< 1	FT-FY19-082018-014059-B	< 1	
WS-014060	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1103A	High Left	WF-08092018-014060	8/19/2018	FT-FY19-082018-014060-A	< 1	FT-FY19-082018-014060-B	2.3
WS-014061	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1103A	Low Right	WF-08092018-014061	8/19/2018	FT-FY19-082018-014061-A	< 1	FT-FY19-082018-014061-B	< 1
WS-014062	8/9/2018	8/9/2019	1	Bottle Filler	In hallway across from auditorium 1206	WF-08092018-014062	8/19/2018	FT-FY19-082018-014062-A	< 1	FT-FY19-082018-014062-B	< 1	
WS-014063	8/8/2018	8/8/2019	1	Cooler	In hallway across from auditorium 1206	High Left	WF-08082018-014063	8/19/2018	FT-FY19-082018-014063-A	< 1	FT-FY19-082018-014063-B	< 1
WS-014064	8/9/2018	8/9/2019	1	Cooler	In hallway across from auditorium 1206	Low Right	WF-08092018-014064	8/19/2018	FT-FY19-082018-014064-A	< 1	FT-FY19-082018-014064-B	< 1
WS-014065	8/9/2018	8/9/2019	1	Bottle Filler	In hallway adjacent to all gender restroom 1221	WF-08092018-014065	8/19/2018	FT-FY19-082018-014065-A	< 1	FT-FY19-082018-014065-B	< 1	
WS-014066	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1221	High Left	WF-08092018-014066	8/19/2018	FT-FY19-082018-014066-A	< 1	FT-FY19-082018-014066-B	1.4
WS-014067	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1221	Low Right	WF-08092018-014067	8/19/2018	FT-FY19-082018-014067-A	< 1	FT-FY19-082018-014067-B	< 1
WS-014069	8/9/2018	8/9/2019	1	Break Room	In admin suite 1207A-F	WF-08092018-014069	8/19/2018	FT-FY19-082018-014069-A	< 1	FT-FY19-082018-014069-B	< 1	
WS-014070	8/9/2018	8/9/2019	1	Bottle Filler	In hallway adjacent to all gender restroom 1230	WF-08092018-014070	8/19/2018	FT-FY19-082018-014070-A	< 1	FT-FY19-082018-014070-B	< 1	
WS-014071	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1230	High Left	WF-08092018-014071	8/19/2018	FT-FY19-082018-014071-A	1.1	FT-FY19-082018-014071-B	< 1
WS-014072	8/9/2018	8/9/2019	1	Cooler	In hallway adjacent to all gender restroom 1230	Low Right	WF-08092018-014072	8/19/2018	FT-FY19-082018-014072-A	< 1	FT-FY19-082018-014072-B	< 1
WS-014074	8/9/2018	8/9/2019	1	Combo Fountain	In music room 1235	WF-08092018-014074	8/19/2018	FT-FY19-082018-014074-A	1.8	FT-FY19-082018-014074-B	< 1	
WS-014076	8/9/2018	8/9/2019	1	Combo Fountain	In choral room 1233	WF-08092018-014076	8/19/2018	FT-FY19-082018-014076-A	< 1	FT-FY19-082018-014076-B	< 1	
WS-014077	8/9/2018	8/9/2019	1	Health Suite	In health suite treatment room 1231D	WF-08092018-014077	8/19/2018	FT-FY19-082018-014077-A	< 1	FT-FY19-082018-014077-B	< 1	
WS-014078	8/9/2018	8/9/2019	1	Bottle Filler	In cafeteria adjacent to stair 9 exit	WF-08092018-014078	8/19/2018	FT-FY19-082018-014078-A	< 1	FT-FY19-082018-014078-B	< 1	
WS-014080	8/9/2018	8/9/2019	1	Cooler	In cafeteria adjacent to stair 9 exit	Low Right	WF-08092018-014080	8/19/2018	FT-FY19-082018-014080-A	< 1	FT-FY19-082018-014080-B	< 1
WS-014089	8/9/2018	8/9/2019	2	Bottle Filler	In hallway adjacent to all gender restroom 2103A	WF-08092018-014089	8/19/2018	FT-FY19-082018-014089-A	< 1	FT-FY19-082018-014089-B	< 1	
WS-014090	8/9/2018	8/9/2019	2	Cooler	In hallway adjacent to all gender restroom 2103A	High Left	WF-08092018-014090	8/19/2018	FT-FY19-082018-014090-A	< 1	FT-FY19-082018-014090-B	2.7
WS-014091	8/9/2018	8/9/2019	2	Cooler	In hallway adjacent to all gender restroom 2103A	Low Right	WF-08092018-014091	8/19/2018	FT-FY19-082018-014091-A	< 1	FT-FY19-082018-014091-B	< 1
WS-014092	8/9/2018	8/9/2019	2	Bottle Filler	In hallway adjacent to electrical room 2205A	WF-08092018-014092	8/19/2018	FT-FY19-082018-014092-A	1.4	FT-FY19-082018-014092-B	< 1	
WS-014093	8/9/2018	8/9/2019	2	Cooler	In hallway adjacent to electrical room 2205A	High Left	WF-08092018-014093	8/19/2018	FT-FY19-082018-014093-A	< 1	FT-FY19-082018-014093-B	< 1
WS-014094	8/9/2018	8/9/2019	2	Cooler	In hallway adjacent to electrical room 2205A	Low Right	WF-08092018-014094	8/19/2018	FT-FY19-082018-014094-A	< 1	FT-FY19-082018-014094-B	< 1
WS-014128	8/9/2018	8/9/2019	2	Health Suite	In training room 2303	WF-08092018-014128	8/19/2018	FT-FY19-082018-014128-A	< 1	FT-FY19-082018-014128-B	< 1	
WS-014131	8/9/2018	8/9/2019	2	Bottle Filler	In hallway across from health room 2306	WF-08092018-014131	8/19/2018	FT-FY19-082018-014131-A	< 1	FT-FY19-082018-014131-B	< 1	
WS-014132	8/9/2018	8/9/2019	2	Cooler	In hallway across from health room 2306	High Left	WF-08092018-014132	8/19/2018	FT-FY19-082018-014132-A	< 1	FT-FY19-082018-014132-B	< 1
WS-014133	8/9/2018	8/9/2019	2	Cooler	In hallway across from health room 2306	Low Right	WF-08092018-014133	8/19/2018	FT-FY19-082018-014133-A	< 1	FT-FY19-082018-014133-B	1.1
WS-014135	8/9/2018	8/9/2019	2	Combo Fountain	In health room 2306	WF-08092018-014135	8/19/2018	FT-FY19-082018-014135-A	< 1	FT-FY19-082018-014135-B	< 1	
WS-014136	8/9/2018	8/9/2019	3	Bottle Filler	In hallway adjacent to all gender restroom 3105A	WF-08092018-014136	8/19/2018	FT-FY19-082018-014136-A	3.1	FT-FY19-082018-014136-B	< 1	

WS-014137	8/9/2018	8/9/2019	3	Cooler	In hallway adjacent to all gender restroom 3105A	High Left	WF-08092018-014137	8/19/2018	FT-FY19-082018-014137-A	< 1	FT-FY19-082018-014137-B	< 1
WS-014138	8/9/2018	8/9/2019	3	Cooler	In hallway adjacent to all gender restroom 3105A	Low Right	WF-08092018-014138	8/19/2018	FT-FY19-082018-014138-A	< 1	FT-FY19-082018-014138-B	< 1
WS-014139	8/9/2018	8/9/2019	3	Bottle Filler	In hallway adjacent to SPED 3202		WF-08092018-014139	8/19/2018	FT-FY19-082018-014139-A	2.8	FT-FY19-082018-014139-B	< 1
WS-014140	8/9/2018	8/9/2019	3	Cooler	In hallway adjacent to SPED 3202	High Left	WF-08092018-014140	8/19/2018	FT-FY19-082018-014140-A	< 1	FT-FY19-082018-014140-B	< 1
WS-014141	8/9/2018	8/9/2019	3	Cooler	In hallway adjacent to SPED 3202	Low Right	WF-08092018-014141	8/19/2018	FT-FY19-082018-014141-A	1	FT-FY19-082018-014141-B	< 1
WS-014142	8/9/2018	8/9/2019	3	Bottle Filler	In hallway adjacent to PE office 3304		WF-08092018-014142	8/19/2018	FT-FY19-082018-014142-A	< 1	FT-FY19-082018-014142-B	< 1
WS-014143	8/8/2018	8/8/2019	3	Cooler	In hallway adjacent to PE office 3304	High Left	WF-08082018-014143	8/19/2018	FT-FY19-082018-014143-A	< 1	FT-FY19-082018-014143-B	< 1
WS-014144	8/9/2018	8/9/2019	3	Cooler	In hallway adjacent to PE office 3304	Low Right	WF-08092018-014144	8/19/2018	FT-FY19-082018-014144-A	4.7	FT-FY19-082018-014144-B	1.2
WS-014145	8/8/2018	8/8/2019	Basement	Combo Fountain	In op/pt office		WF-08082018-014145	8/19/2018	FT-FY19-082018-014145-A	< 1	FT-FY19-082018-014145-B	< 1

Food Prep Sink

Greater than 5ppb - Devices requiring remediation									
Record ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-014084	1	Food Prep Sink	In kitchen	8/19/2018	FT-FY19-082018-014084-A	< 1	FT-FY19-082018-014084-B	7.7	

First Re-test (After Plumbing Check)

Food Prep Sink

Less than 5ppb - Devices requiring no remediation									
Record ID	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS-014084	1	Food Prep Sink	In kitchen	WF-08232018-014084	8/30/2018	FT-FY19-082018-014084-A	1.3	FT-FY19-082018-014084-B	< 1