



MALCOLM X LEAD WATER TEST RESULTS

May 24th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	MALCOLM X ELEMENTARY	5/12/2016	WS- 009885	Utility	Basement	In boiler room (water source)	WT-042916-9902- A	326	WT-042916-9902- B	< 2	Non-drinking water source - Not accessible to children			
2	MALCOLM X ELEMENTARY	5/12/2016	WS- 009886	Kitchen	1	In kitchen clock wise 1	WT-042916-9903- A	< 2	WT-042916-9903- B	< 2				
3	MALCOLM X ELEMENTARY	5/12/2016	WS- 009887	Kitchen	1	In kitchen clock wise 2	WT-042916-9904- A	< 2	WT-042916-9904- B	< 2				
4	MALCOLM X ELEMENTARY	5/12/2016	WS- 009888	Cooler	1	In multipurpose room	WT-042916-9905- A	< 2	WT-042916-9905- B	< 2				
5	MALCOLM X ELEMENTARY	5/12/2016	WS- 009889	Cooler	1	In health suite	WT-042916-9906- A	10	WT-042916-9906- B	2.8				
6	MALCOLM X ELEMENTARY	5/12/2016	WS- 009890	Break Room	1	Teachers lounge	WT-042916-9907- A	< 2	WT-042916-9907- B	< 2				
7	MALCOLM X ELEMENTARY	5/12/2016	WS- 009891	Cooler	1	In hallway adjacent to 109	WT-042916-9908- A	< 2	WT-042916-9908- B	< 2				
8	MALCOLM X ELEMENTARY	5/12/2016	WS- 009892	Classroom	1	In room 109	WT-042916-9909- A	< 2	WT-042916-9909- B	< 2				
9	MALCOLM X ELEMENTARY	5/12/2016	WS- 009893	Cooler	1	In hallway adjacent to room 115	WT-042916-9910- A	< 2	WT-042916-9910- B	< 2				
10	MALCOLM X ELEMENTARY	5/12/2016	WS- 009894	Cooler	1	In hallway across from room 132	WT-042916-9911- A	< 2	WT-042916-9911- B	< 2				
11	MALCOLM X ELEMENTARY	5/12/2016	WS- 009895	Fountain	1	In room 130	WT-042916-9912- A	< 2	WT-042916-9912- B	< 2				
12	MALCOLM X ELEMENTARY	5/12/2016	WS- 009896	Classroom	1	In room 130	WT-042916-9913- A	< 2	WT-042916-9913- B	< 2				
13	MALCOLM X ELEMENTARY	5/12/2016	WS- 009897	Cooler	1	In room131	WT-042916-9914- A	< 2	WT-042916-9914- B	< 2				
14	MALCOLM X ELEMENTARY	5/12/2016	WS- 009898	Classroom	1	In room131	WT-042916-9915- A	< 2	WT-042916-9915- B	< 2				
15	MALCOLM X ELEMENTARY	5/12/2016	WS- 009899	Classroom	2	In room 202	WT-042916-9916- A	4.3	WT-042916-9916- B	9.2				
16	MALCOLM X ELEMENTARY	5/12/2016	WS- 009900	Cooler	2	In hallway adjacent to room 208	WT-042916-9917- A	< 2	WT-042916-9917- B	< 2				
17	MALCOLM X ELEMENTARY	5/12/2016	WS- 009901	Cooler	2	In hallway across from room 202	WT-042916-9918- A	< 2	WT-042916-9918- B	< 2				
18	MALCOLM X ELEMENTARY	5/12/2016	WS- 009902	Cooler	2	In hallway adjacent to room 218	WT-042916-9919- A	< 2	WT-042916-9919- B	< 2				
19	MALCOLM X ELEMENTARY	5/12/2016	WS- 009903	Classroom	2	In room 224 Left	WT-042916-9920- A	< 2	WT-042916-9920- B	< 2				
20	MALCOLM X ELEMENTARY	5/12/2016	WS- 009904	Fountain	2	In room 224	WT-042916-9921- A	< 2	WT-042916-9921- B	< 2				
21	MALCOLM X ELEMENTARY	5/12/2016	WS- 009905	Classroom	2	In room 225 Left	WT-042916-9922- A	4.8	WT-042916-9922- B	3.6				
22	MALCOLM X ELEMENTARY	5/12/2016	WS- 009906	Classroom	2	In room 225 Right	WT-042916-9923- A	< 2	WT-042916-9923- B	< 2				
23	MALCOLM X ELEMENTARY	5/12/2016	WS- 009907	Cooler	3	In hallway adjacent to room 308	WT-042916-9924- A	< 2	WT-042916-9924- B	4.1				
24	MALCOLM X ELEMENTARY	5/12/2016	WS- 009908	Cooler	3	In hallway across to room 303	WT-042916-9925- A	< 2	WT-042916-9925- B	< 2				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.