



# Malcolm X ES Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation											
RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 009890	6/19/2017	6/19/2018	1	Break Room	In staff lounge	WF-62017-009890	11/20/2017	FT-FY18--62017-009890-A	<1	FT-FY18--62017-009890-B	<1
WS- 009891	6/19/2017	6/19/2018	1	Cooler	In hallway adjacent to room 109	WF-62017-009891	11/20/2017	FT-FY18--62017-009891-A	<1	FT-FY18--62017-009891-B	<1
WS- 009895	6/19/2017	6/19/2018	1	Fountain	In classroom 130	WF-62017-009895	11/20/2017	FT-FY18--62017-009895-A	<1	FT-FY18--62017-009895-B	<1
WS- 009898	11/7/2017	11/7/2018	1	Classroom Faucet	In classroom 131	WF-112017-009898	11/20/2017	FT-FY18-112017-009898-A	<1	FT-FY18-112017-009898-B	<1
WS- 009903	11/7/2017	11/7/2018	2	Combo Faucet	In classroom 224	WF-112017-009903	11/20/2017	FT-FY18-112017-009903-A	<1	FT-FY18-112017-009903-B	<1
WS- 009906	6/19/2017	6/19/2018	2	Combo Fountain	In classroom 225	WF-62017-009906	11/20/2017	FT-FY18--62017-009906-A	<1	FT-FY18--62017-009906-B	<1
WS- 009907	6/19/2017	6/19/2018	3	Cooler	In hallway adjacent to room 308	WF-62017-009907	11/20/2017	FT-FY18--62017-009907-A	<1	FT-FY18--62017-009907-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation									
RECORD ID	Floor	Device Type	Device Location	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 009887	1	Food Prep Sink	In kitchen second clockwise from entry door	11/20/2017	FT-FY18-102017-009887-A	<1	FT-FY18-102017-009887-B	<1	