



MANN LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003934	Utility	Basement	In boiler room	Right Low	WT-042916-3951-A	228	WT-042916-3951-B	142	Non-drinking water source - Not accessible to children		
2 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003935	Classroom	1	In classroom 150	Left High	WT-042916-3952-A	< 1	WT-042916-3952-B	< 1			
3 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003936	Fountain	1	In classroom 150	Right Low	WT-042916-3953-A	< 1	WT-042916-3953-B	< 1			
4 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003937	Classroom	1	In classroom 146	Left High	WT-042916-3954-A	< 1	WT-042916-3954-B	< 1			
5 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003938	Fountain	1	In classroom 146	Right Low	WT-042916-3955-A	< 1	WT-042916-3955-B	< 1			
6 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003939	Fountain	1	In classroom 142	Right Low	WT-042916-3956-A	1.01	WT-042916-3956-B	< 1			
7 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003940	Classroom	1	In classroom 142	Right High	WT-042916-3957-A	1.52	WT-042916-3957-B	< 1			
8 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003941	Fountain	1	In classroom 154	Right Low	WT-042916-3958-A	< 1	WT-042916-3958-B	< 1			
9 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003942	Classroom	1	In classroom 154	Left High	WT-042916-3959-A	< 1	WT-042916-3959-B	< 1			
10 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003943	Fountain	1	In classroom 138	Right Low	WT-042916-3960-A	< 1	WT-042916-3960-B	< 1			
11 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003944	Classroom	1	In classroom 138	Mid High	WT-042916-3961-A	< 1	WT-042916-3961-B	< 1			
12 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003945	Cooler	1	In hallway adjacent to janitor closet room 156A	Mid Low	WT-042916-3962-A	< 1	WT-042916-3962-B	< 1			
13 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003946	Cooler	2	In hallway adjacent to classroom 229	Left Low	WT-042916-3963-A	< 1	WT-042916-3963-B	< 1			
14 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003947	Fountain	2	In hallway adjacent to classroom 235	Mid Low	WT-042916-3964-A	< 1	WT-042916-3964-B	< 1			
15 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003948	Kitchen	1	In kitchen west center wall west wing	Right Low	WT-042916-3965-A	< 1	WT-042916-3965-B	< 1			
16 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003949	Kitchen	1	In kitchen west center wall west wing	Right High	WT-042916-3966-A	< 1	WT-042916-3966-B	< 1			
17 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003950	Kitchen	1	In kitchen east wall west wing	Right High	WT-042916-3967-A	< 1	WT-042916-3967-B	< 1			
18 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003951	Kitchen	1	In kitchen on north wall west wing	Mid High	WT-042916-3968-A	< 1	WT-042916-3968-B	< 1			
19 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003952	Cooler	1	In hallway adjacent to room 110	Mid High	WT-042916-3969-A	< 1	WT-042916-3969-B	< 1			
20 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003953	Cooler	1	In hallway adjacent to principal office room 134	Mid Low	WT-042916-3970-A	< 1	WT-042916-3970-B	< 1			
21 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003954	Classroom	1	In classroom 103	Right High	WT-042916-3971-A	1.51	WT-042916-3971-B	< 1			
22 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003955	Classroom	1	In classroom 103	Left High	WT-042916-3972-A	< 1	WT-042916-3972-B	< 1			
23 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003956	Classroom	1	In teachers lounge in classroom 133	Left High	WT-042916-3973-A	< 1	WT-042916-3973-B	< 1			
24 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003957	Other	1	In teacher lounge 133 (spray nozzle)	Right Low	WT-042916-3974-A	< 1	WT-042916-3974-B	< 1			
25 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003958	Classroom	2	In classroom 203	Left High	WT-042916-3975-A	1.52	WT-042916-3975-B	< 1			
26 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003959	Other	2	In classroom 203 spray nozzle	Right Low	WT-042916-3976-A	< 1	WT-042916-3976-B	< 1			
27 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003960	Cooler	3	In hallway adjacent to elevator machine room	Left Low	WT-042916-3977-A	< 1	WT-042916-3977-B	< 1			
28 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003961	Cooler	2	In hallway adjacent to teacher workroom room 226	Mid Low	WT-042916-3978-A	< 1	WT-042916-3978-B	< 1			
29 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003962	Cooler	3	In hallway adjacent to classroom 302	Right Low	WT-042916-3979-A	< 1	WT-042916-3979-B	< 1			
30 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003963	Cooler	1	In hallway adjacent to room 150	Left High	WT-042916-3980-A	< 1	WT-042916-3980-B	< 1			
31 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003964	Classroom	3	In class room 302	Left High	WT-042916-3981-A	< 1	WT-042916-3981-B	< 1			
32 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003965	Other	3	In classroom 302-spray nozzle	Right Low	WT-042916-3982-A	< 1	WT-042916-3982-B	< 1			
33 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003966	Classroom	1	In art room 104	Right	WT-042916-3983-A	< 1	WT-042916-3983-B	< 1			
34 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003967	Classroom	1	In art room 104	Left	WT-042916-3984-A	< 1	WT-042916-3984-B	< 1			
35 MANN ELEMENTARY SCHOOL	5/6/2016	WS-003968	Cooler	2	In hallway adjacent to room 216	Left	WT-042916-3985-A	< 1	WT-042916-3985-B	< 1			

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.