



Marvin Gaye Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000470	1/18/2023	1/18/2024	1	Food Prep Sink	In teaching kitchen	WF-01182023-000470	02/21/2023	FT-FY23-02022023-000470-A	<1	FT-FY23-02022023-000470-B	<1
WS- 000471	5/2/2022	5/2/2023	2	Bottle Filler	In hallway adjacent to music room 202	WF-05022022-000471	02/21/2023	FT-FY23-02022023-000471-A	<1	FT-FY23-02022023-000471-B	<1
WS- 000472	5/2/2022	5/2/2023	2	Cooler	In hallway adjacent to music room 202	WF-05022022-000472	02/21/2023	FT-FY23-02022023-000472-A	<1	FT-FY23-02022023-000472-B	<1