



MARVIN GAYE REC LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006152	Kitchen	1	In rec center in closet adjacent to women's bathroom	WT-042916-6169- A	< 1	WT-042916-6169- B	< 1				
2 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006153	Other	1	In rec center in closet adjacent to women's bathroom (spray nozzle)	WT-042916-6170- A	< 1	WT-042916-6170- B	< 1				
3 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006154	Fountain	1	In rec center	WT-042916-6171- A	< 1	WT-042916-6171- B	< 1				
4 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006155	Fountain	1	In rec center	WT-042916-6172- A	< 1	WT-042916-6172- B	< 1				
5 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006156	Fountain	Ground Floor	Exterior adjacent to basketball courts	WT-042916-6173- A	1.1	WT-042916-6173- B	< 1				
6 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006157	Fountain	Ground Floor	Exterior of rec center adjacent to basketball court	WT-042916-6174- A	3	WT-042916-6174- B	< 1				
7 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006158	Fountain	Ground Floor	Exterior inside of playground	WT-042916-6175- A	3.3	WT-042916-6175- B	< 1				
8 MARVIN GAYE RECREATION CENTER	5/27/2016	WS- 006159	Fountain	Ground Floor	Exterior in playground (bottle filler)	WT-042916-6176- A	< 1	WT-042916-6176- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.