



MAURY LEAD WATER TEST RESULTS

May 16th, 2016



Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008469	Utility	Basement	In boiler room	WT-042916-8486- A	10.1	WT-042916-8486- B	< 1				
2 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008470	Classroom	Basement	In classroom w030 Left	WT-042916-8487- A	< 1	WT-042916-8487- B	< 1				
3 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008471	Fountain	Basement	In classroom w030 Right	WT-042916-8488- A	< 1	WT-042916-8488- B	< 1				
4 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008472	Cooler	Basement	In hallway adjacent to room W022 Right Low	WT-042916-8489- A	< 1	WT-042916-8489- B	< 1				
5 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008473	Cooler	Basement	In hallway adjacent to room W022 Left High	WT-042916-8490- A	< 1	WT-042916-8490- B	< 1				
6 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008474	Classroom	Basement	In classroom W010 Left	WT-042916-8491- A	2.4	WT-042916-8491- B	< 1				
7 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008475	Fountain	Basement	In classroom W010 Right	WT-042916-8492- A	< 1	WT-042916-8492- B	< 1				
8 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008476	Classroom	1	In health suit E 143	WT-042916-8493- A	< 1	WT-042916-8493- B	< 1				
9 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008477	Classroom	1	In classroom E 135	WT-042916-8494- A	< 1	WT-042916-8494- B	< 1				
10 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008478	Fountain	1	In classroom E 135	WT-042916-8495- A	< 1	WT-042916-8495- B	< 1				
11 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008479	Fountain	1	In classroom E140	WT-042916-8496- A	< 1	WT-042916-8496- B	< 1				
12 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008480	Classroom	1	In classroom E140	WT-042916-8497- A	1.15	WT-042916-8497- B	< 1				
13 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008481	Classroom	1	In work room E 134	WT-042916-8498- A	< 1	WT-042916-8498- B	< 1				
14 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008482	Fountain	1	In classroom E125	WT-042916-8499- A	< 1	WT-042916-8499- B	< 1				
15 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008483	Classroom	1	In classroom E125	WT-042916-8500- A	< 1	WT-042916-8500- B	< 1				
16 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008484	Other	1	In work room E0 134 (spray nozzle)	WT-042916-8501- A	1.06	WT-042916-8501- B	< 1				
17 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008485	Cooler	1	In hallway adjacent to room E121	WT-042916-8502- A	< 1	WT-042916-8502- B	< 1				
18 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008486	Cooler	1	In classroom E110	WT-042916-8503- A	< 1	WT-042916-8503- B	< 1				
19 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008487	Kitchen	1	In kitchen Low	WT-042916-8504- A	< 1	WT-042916-8504- B	< 1				
20 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008488	Other	1	In kitchen (spray nozzle) High	WT-042916-8505- A	< 1	WT-042916-8505- B	< 1				
21 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008489	Cooler	2	In stairway 4	WT-042916-8506- A	< 1	WT-042916-8506- B	< 1				
22 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008490	Cooler	3	In stairway 4	WT-042916-8507- A	< 1	WT-042916-8507- B	< 1				
23 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008491	Cooler	2	In hallway adjacent to room E220	WT-042916-8508- A	< 1	WT-042916-8508- B	< 1				
24 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008492	Classroom	2	In classroom E 220 Left	WT-042916-8509- A	< 1	WT-042916-8509- B	1.23				
25 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008493	Classroom	2	In classroom E 220 Right	WT-042916-8510- A	< 1	WT-042916-8510- B	< 1				
26 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008494	Fountain	2	In classroom E230	WT-042916-8511- A	< 1	WT-042916-8511- B	< 1				
27 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008495	Classroom	2	In classroom E230	WT-042916-8512- A	< 1	WT-042916-8512- B	< 1				
28 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008496	Break Room	2	In room E235	WT-042916-8513- A	2.41	WT-042916-8513- B	1.39				
29 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008497	Other	2	In room E235 (spray nozzle)	WT-042916-8514- A	1.89	WT-042916-8514- B	1.27				
30 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008498	Classroom	2	In classroom E 240	WT-042916-8515- A	1.01	WT-042916-8515- B	< 1				
31 MAURY ELEMENTARY SCHOOL	5/6/2016	WS- 008499	Fountain	2	In classroom E 240	WT-042916-8516- A	< 1	WT-042916-8516- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.