



McKinley Tech HS Lead in Water Test Results



FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 002590	6/3/2019	6/3/2020	Basement	Cooler	In girls' locker room adjacent to room G-119	WF-06032019-002590	1/6/2020	FT-FY20-122019-002590-A	<1	FT-FY20-122019-002590-B	<1	
WS- 002591	6/3/2019	6/3/2020	Basement	Cooler	In boy's' locker room adjacent to room G-124	WF-06032019-002591	1/6/2020	FT-FY20-122019-002591-A	<1	FT-FY20-122019-002591-B	<1	
WS- 010490	6/3/2019	6/3/2020	3	Cooler	In hallway adjacent to room 365	WF-06032019-010490	1/6/2020	FT-FY20-122019-010490-A	<1	FT-FY20-122019-010490-B	<1	
WS- 010491	6/3/2019	6/3/2020	3	Cooler	In hallway across from room 368	WF-06032019-010491	1/6/2020	FT-FY20-122019-010491-A	<1	FT-FY20-122019-010491-B	<1	
WS- 011747	6/3/2019	6/3/2020	2	Cooler	In hallway across from boys' restroom	WF-06032019-011747	1/6/2020	FT-FY20-122019-011747-A	<1	FT-FY20-122019-011747-B	<1	
WS- 011748	6/3/2019	6/3/2020	2	Cooler	In hallway across from girl's restroom	WF-06032019-011748	1/6/2020	FT-FY20-122019-011748-A	<1	FT-FY20-122019-011748-B	<1	
WS- 011800	6/3/2019	6/3/2020	1	Health Suite	In health suite 156B	WF-06032019-011800	1/6/2020	FT-FY20-122019-011800-A	<1	FT-FY20-122019-011800-B	<1	
WS- 011801	6/3/2019	6/3/2020	1	Health Suite	In health suite 156D	WF-06032019-011801	1/6/2020	FT-FY20-122019-011801-A	<1	FT-FY20-122019-011801-B	<1	
WS- 011802	6/3/2019	6/3/2020	1	Health Suite	In health suite 156E	WF-06032019-011802	1/6/2020	FT-FY20-122019-011802-A	<1	FT-FY20-122019-011802-B	<1	
WS- 011803	6/3/2019	6/3/2020	1	Cooler	In hallway adjacent to restroom 163T	WF-06032019-011803	1/6/2020	FT-FY20-122019-011803-A	<1	FT-FY20-122019-011803-B	<1	
WS- 011808	6/3/2019	6/3/2020	1	Cooler	In gym adjacent to room G212	Low Left	WF-06032019-011808	1/6/2020	FT-FY20-122019-011808-A	<1	FT-FY20-122019-011808-B	<1
WS- 011810	6/3/2019	6/3/2020	Basement	Cooler	In gym adjacent to room G115	Low Left	WF-06032019-011810	1/6/2020	FT-FY20-122019-011810-A	<1	FT-FY20-122019-011810-B	<1
WS- 011811	6/3/2019	6/3/2020	Basement	Cooler	In gym adjacent to room G115	High Right	WF-06032019-011811	1/6/2020	FT-FY20-122019-011811-A	<1	FT-FY20-122019-011811-B	<1
WS- 011812	6/3/2019	6/3/2020	Basement	Cooler	In hallway adjacent to room G102T	Low Left	WF-06032019-011812	1/6/2020	FT-FY20-122019-011812-A	<1	FT-FY20-122019-011812-B	<1
WS- 011822	6/3/2019	6/3/2020	Basement	Ice Maker	In kitchen (ice maker)		WF-06032019-011822	1/6/2020	FT-FY20-122019-011822-A	<1	FT-FY20-122019-011822-B	<1
WS- 011825	6/3/2019	6/3/2020	1	Cooler	In hallway adjacent to room 161T		WF-06032019-011825	1/6/2020	FT-FY20-122019-011825-A	<1	FT-FY20-122019-011825-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011820	7/3/2019	7/3/2020	Basement	Food Prep Sink	In kitchen east wall	Left	WF-07032019-011820	1/6/2020	FT-FY20-122019-011820-A	<1	FT-FY20-122019-011820-B	<1