



# MITCHELL PARK REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location		1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005525	Fountain	Ground Floor	Exterior sitting area adjacent between athletic field and office	Low	WT-042916-5542- A	< 1	WT-042916-5542- B	< 1				
2	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005526	Fountain	Ground Floor	Exterior sitting area adjacent between athletic field and office	High	WT-042916-5543- A	< 1	WT-042916-5543- B	< 1				
3	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005527	Fountain	Ground Floor	Exterior sitting area adjacent between athletic field and office (dog fountain)	Low	WT-042916-5544- A	< 1	WT-042916-5544- B	< 1				
4	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005530	Cooler	1	In recreation center main day room		WT-042916-5547- A	< 1	WT-042916-5547- B	< 1				
5	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005531	Fountain	Ground Floor	Exterior between office and Bancroft St entrance	High	WT-042916-5548- A	< 1	WT-042916-5548- B	< 1				
6	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005532	Fountain	Ground Floor	Exterior between office and Bancroft St entrance	Low	WT-042916-5549- A	< 1	WT-042916-5549- B	< 1				
7	MITCHELL PARK RECREATION CENTER	5/27/2016	WS- 005533	Fountain	Ground Floor	Exterior between office and Bancroft St entrance (dog fountain)	Low	WT-042916-5550- A	< 1	WT-042916-5550- B	< 1				

Footnotes:

- A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.
- B - Second draw sample is collected after a 60 second flush at that device after the first draw.