



## MURCH LEAD WATER TEST RESULTS

May 15, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003747	Utility	Basement	In boiler room (Main water source)	WT-042916-3764- A	1.3	WT-042916-3764- B	< 1				
2	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003748	Cooler	1	In hallway adjacent to room 101	WT-042916-3765- A	< 1	WT-042916-3765- B	< 1				
3	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003749	Kitchen	1	In kitchen	WT-042916-3766- A	< 1	WT-042916-3766- B	< 1				
4	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003750	Cooler	1	In auditorium	WT-042916-3767- A	< 1	WT-042916-3767- B	< 1				
5	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003751	Cooler	1	In health suite Right	WT-042916-3768- A	< 1	WT-042916-3768- B	< 1				
6	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003752	Cooler	1	In health suite Left	WT-042916-3769- A	1.3	WT-042916-3769- B	< 1				
7	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003753	Cooler	1	In hallway adjacent to boy's bathroom	WT-042916-3770- A	1.8	WT-042916-3770- B	< 1				
8	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003754	Cooler	1	In room 110	WT-042916-3771- A	1.4	WT-042916-3771- B	< 1				
9	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003755	Cooler	1	In hallway adjacent to girl's bathroom	WT-042916-3772- A	< 1	WT-042916-3772- B	< 1				
10	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003756	Classroom	1	In room K5	WT-042916-3773- A	< 1	WT-042916-3773- B	< 1				
11	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003757	Classroom	1	In room 102 Right	WT-042916-3774- A	2.1	WT-042916-3774- B	< 1				
12	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003758	Classroom	1	In room 102 Left	WT-042916-3775- A	< 1	WT-042916-3775- B	< 1				
13	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003759	Classroom	1	In room K5 back wall	WT-042916-3776- A	< 1	WT-042916-3776- B	< 1				
14	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003760	Cooler	1	In hallway adjacent to room K5	WT-042916-3777- A	< 1	WT-042916-3777- B	< 1				
15	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003761	Break Room	1	In teacher's lounge	WT-042916-3778- A	1.2	WT-042916-3778- B	< 1				
16	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003763	Classroom	1	In classroom K2	WT-042916-3780- A	< 1	WT-042916-3780- B	< 1				
17	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003764	Cooler	1	In room K1 Left	WT-042916-3781- A	< 1	WT-042916-3781- B	< 1				
18	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003765	Classroom	2	In room 208	WT-042916-3782- A	1.7	WT-042916-3782- B	< 1				
19	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003766	Cooler	2	In hallway adjacent to boy's bathroom	WT-042916-3783- A	< 1	WT-042916-3783- B	< 1				
20	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003767	Cooler	2	In hallway adjacent to room 200	WT-042916-3784- A	< 1	WT-042916-3784- B	< 1				
21	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003768	Classroom	2	In room 202	WT-042916-3785- A	5.4	WT-042916-3785- B	1.2				
22	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003769	Cooler	2	In hallway adjacent to room 204	WT-042916-3786- A	< 1	WT-042916-3786- B	< 1				
23	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003770	Other	2	In counselor's office	WT-042916-3787- A	29	WT-042916-3787- B	3.4	Filter will be installed and then retested			
24	MURCH ELEMENTARY SCHOOL	5/7/2016	WS-003771	Fountain	1	In room K1 Right	WT-042916-3788- A	< 1	WT-042916-3788- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.