


mulch and weeding needed



large tree to be preserved, root zone to be evaluated for aeration










SITE ACCESSIBILITY







drinking fountain



bike racks



bench




trash & recycling receptacle




park signs

















KOM PA N

