



New York Ave Recreation Center Lead in Water Test Results

FY23 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006131	3/7/2022	3/7/2023	Ground Floor	Cooler	In hallway adjacent to janitor closet	WF-03072022-006131	2/17/2023	FT-FY23-02022023-006131-A	<1	FT-FY23-02022023-006131-B	<1
WS- 006132	1/25/2023	1/25/2024	Ground Floor	Food Prep Sink	In kitchen adjacent to men's restroom	WF-01252023-006132	2/17/2023	FT-FY23-02022023-006132-A	<1	FT-FY23-02022023-006132-B	<1