



# New York Avenue Recreation Center Lead in Water Test Results

## FY24 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006131	2/21/2024	2/21/2025	Ground Floor	Cooler	In hallway adjacent to janitor closet	WF-02212024-006131	3/12/2024	FT-FY24-02272024-006131-A	<1	FT-FY24-02272024-006131-B	<1
WS- 006132	12/18/2023	12/18/2024	Ground Floor	Food Prep Sink	In kitchen adjacent to men's restroom	WF-12182023-006132	3/12/2024	FT-FY24-02272024-006132-A	<1	FT-FY24-02272024-006132-B	<1