



NEW YORK AVE REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	New York Ave Recreation Center	5/24/2016	WS- 006131	Cooler	Ground Floor	In rec center adjacent to janitor closet	WT-042916-6148- A	4.8	WT-042916-6148- B	20.8	Filtered	7/1/2016	<1	<1
2	New York Ave Recreation Center	5/24/2016	WS- 006132	Kitchen	Ground Floor	In Kitchen nook adjacent to men's bathroom	WT-042916-6149- A	13.2	WT-042916-6149- B	1.3				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.