



# North Michigan Park RC Lead in Water Test Results



## FY20 Filter Test

Less than 5ppb - Devices requiring no remediation

Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011556	4/24/2019	4/24/2020	1	Cooler	In hallway adjacent to women's restroom	Low Left	WF-04242019-011556	2/26/2020	FT-FY20-012020-011556-A	<1	FT-FY20-012020-011556-B	<1
WS- 011557	4/24/2019	4/24/2020	1	Cooler	In hallway adjacent to women's restroom	High Right	WF-04242019-011557	2/26/2020	FT-FY20-012020-011557-A	<1	FT-FY20-012020-011557-B	<1
WS- 011558	4/24/2019	4/24/2020	1	Cooler	In hallway adjacent to room 104	High Left	WF-04242019-011558	2/26/2020	FT-FY20-012020-011558-A	<1	FT-FY20-012020-011558-B	<1
WS- 011559	4/24/2019	4/24/2020	1	Cooler	In hallway adjacent to room 104	Low Right	WF-04242019-011559	2/26/2020	FT-FY20-012020-011559-A	<1	FT-FY20-012020-011559-B	<1
WS- 011560	4/24/2019	4/24/2020	1	Food Prep Sink	In kitchenette 107 within activity room 108		WF-04242019-011560	2/26/2020	FT-FY20-012020-011560-A	<1	FT-FY20-012020-011560-B	<1
WS- 011561	4/24/2019	4/24/2020	1	Food Prep Sink	In main kitchen within the community room		WF-04242019-011561	2/26/2020	FT-FY20-012020-011561-A	<1	FT-FY20-012020-011561-B	<1