



North Michigan Park RC Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011556	4/15/2021	4/15/2022	1	Cooler	In hallway adjacent to women's restroom	Low	Left	WF-04152021-011556	5/7/2021	FT-FY21-042021-011556-A	<1	FT-FY21-042021-011556-B	<1
WS- 011557	4/15/2021	4/15/2022	1	Cooler	In hallway adjacent to women's restroom	High	Right	WF-04152021-011557	5/7/2021	FT-FY21-042021-011557-A	<1	FT-FY21-042021-011557-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS- 011560	2/23/2021	2/23/2022	1	Food Prep Sink	In kitchenette 107 within activity room 108	WF-02232021-011560	5/7/2021	FT-FY21-042021-011560-A	<1	FT-FY21-042021-011560-B	3.0	
WS- 011561	2/23/2021	2/23/2022	1	Food Prep Sink	In main kitchen within the community room	WF-02232021-011561	5/7/2021	FT-FY21-042021-011561-A	<1	FT-FY21-042021-011561-B	<1	

FY21 Filter Test

Greater than 5ppb - Devices requiring remediation												
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location		Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011558	4/15/2021	4/15/2022	1	Cooler	In hallway adjacent to room 104	High Left	WF-04152021-011558	5/7/2021	FT-FY21-042021-011558-A	28.0	FT-FY21-042021-011558-B	2.1
WS- 011559	4/15/2021	4/15/2022	1	Cooler	In hallway adjacent to room 104	Low Right	WF-04152021-011559	5/7/2021	FT-FY21-042021-011559-A	15.0	FT-FY21-042021-011559-B	4.4

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation													
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location			Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 011558	5/12/2021	5/12/2022	1	Cooler	In hallway adjacent to room 104	High	Left	WF-05122021-011558	5/21/2021	FT-FY21-052021-011558-A	<1	FT-FY21-052021-011558-B	<1
WS- 011559	5/12/2021	5/12/2022	1	Cooler	In hallway adjacent to room 104	Low	Right	WF-05122021-011559	5/21/2021	FT-FY21-052021-011559-A	<1	FT-FY21-052021-011559-B	<1