



## NORTH MICHIGAN PARK REC LEAD WATER TEST RESULTS



	Building Location: Building Name	RECORD ID	Date Analyzed	Floor	Device Type	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)
1	NORTH MICHIGAN PARK RECREATION CENTER	WS- 011558**	9/22/2016	1	Cooler	In hallway adjacent to room 104 High Left	FT-82016-011558-A	8.2	FT-82016-011558-B	1.5
			10/7/2016				Re-test A	< 1	Re-test B	< 1
2	NORTH MICHIGAN PARK RECREATION CENTER	WS- 011559	9/22/2016	1	Cooler	In hallway adjacent to room 104 Low Right	FT-82016-011559-A	< 1	FT-82016-011559-B	< 1
3	NORTH MICHIGAN PARK RECREATION CENTER	WS- 011560**	9/22/2016	1	Food Prep Sink	In kitchen 107	FT-82016-011560-A	1.1	FT-82016-011560-B	< 1
			10/7/2016				Re-test A	< 1	Re-test B	< 1
4	NORTH MICHIGAN PARK RECREATION CENTER	WS- 011561	9/22/2016	1	Food Prep Sink	In kitchen 107	FT-82016-011561-A	< 1	FT-82016-011561-B	< 1

\*\*Filters and plumbing checked and filters re-tested.