



# North Michigan RC Lead Water Test Results



## FY18 Filter Test

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-011557	7/5/17	7/5/18	1	Cooler	In hallway adjacent to women's restroom	Right High	WF-72017-011557	2/16/18	FT-FY18--72017-011557-A	<1	FT-FY18--72017-011557-B	<1
WS-011559	7/5/17	7/5/18	1	Cooler	In hallway adjacent to room 104	Right Low	WF-72017-011559	2/16/18	FT-FY18--72017-011559-A	<1	FT-FY18--72017-011559-B	<1

## Food Prep Sink

Less than 5 ppb - Devices Requiring No Remediation

RECORD ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	WATER FILTERS Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)	
WS-011560	7/5/17	7/5/18	1	Food Prep Sink	In kitchen 107		WF-72017-011560	2/16/18	FT-FY18--72017-011560-A	<1	FT-FY18--72017-011560-B	<1